



0006177298

90-890000070

Form Approved OMB No. 2010-0019 Approval Expires 12-31-89

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Comprehensive Assessment Information Rule

REPORTING FORM

CONTAINS NO CBI

When completed, send this form to:

Document Processing Center Office of Toxic Substances, TS-790 U.S. Environmental Protection Agency 401 M Street, SW Washington, DC 20460 Attention: CAIR Reporting Office For Agency Use Only:

Date of Receipt: _____

Document
Control Number:

Docket Number:

PART	Α (GENERAL REPORTING INFORMATION
1.01	Th	is Comprehensive Assessment Information Rule (CAIR) Reporting Form has been
1.01		
CBI	cor	npleted in response to the <u>Federal Register</u> Notice of $[\overline{f}]\overline{2}$ $[\overline{z}]\overline{5}$ $[\overline{8}]\overline{5}$ year
[_]	a.	If a Chemical Abstracts Service Number (CAS No.) is provided in the Federal
		Register, list the CAS No $[0]0]1]3]2]1]-[3]8]-[6]$
	b.	If a chemical substance CAS No. is not provided in the <u>Federal Register</u> , list either (i) the chemical name, (ii) the mixture name, or (iii) the trade name of the chemical substance as provided in the <u>Federal Register</u> .
		(i) Chemical name as listed in the rule
		(ii) Name of mixture as listed in the rule
		(iii) Trade name as listed in the rule
	c.	If a chemical category is provided in the <u>Federal Register</u> , report the name of the category as listed in the rule, the chemical substance CAS No. you are reporting on which falls under the listed category, and the chemical name of the substance you are reporting on which falls under the listed category.
		Name of category as listed in the rule
		CAS No. of chemical substance [_]_]_]_]_]_]_]_]_]_[_]
		Name of chemical substance
1.02	Ide	ntify your reporting status under CAIR by circling the appropriate response(s).
<u>CBI</u>	Man	ufacturer 1
[_]	Imp	orter 2
	Pro	cessor
	X/P	manufacturer reporting for customer who is a processor 4
	X/P	processor reporting for customer who is a processor

∨1.03 <u>CBI</u> [_]	Does the substance you are reporting on have an "x/p" designation associated with it in the above-listed Federal Register Notice? Yes
CBI	a. Do you manufacture, import, or process the listed substance and distribute it under a trade name(s) different than that listed in the Federal Register Notice? Circle the appropriate response. Yes
1.05	[] You have chosen to report for your customers [] You have submitted the trade name(s) to EPA one day after the effective date of the rule in the Federal Register Notice under which you are reporting. If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name.
[_]	Trade name
1.06 <u>CBI</u> []	Certification — The person who is responsible for the completion of this form must sign the certification statement below: "I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate." DOUGLAS L. GIBSON NAME SIGNATURE DATE SIGNED TITLE TELEPHONE NO.
[<u></u>] M	ark (X) this box if you attach a continuation sheet.

1.07 <u>CBI</u> []	Exemptions From Reporting with the required information within the past 3 years, and for the time period specified are required to complete sections required but not previous submissions along with your Section 1.	on a CAIF this infor in the ru ion 1 of t ly submitt	R Reporting Form for the mation is current, accurule, then sign the certifications CAIR form and providued. Provide a copy of a	listed substance ate, and complete ication below. You be any information
	"I hereby certify that, to the information which I have not it to EPA within the past 3 years period specified in the rule."	included i s and is c	n this CAIR Reporting Fo	rm has been submitted
	NAME	_	SIGNATURE	DATE SIGNED
		() -	
	TITLE		TELEPHONE NO.	DATE OF PREVIOUS SUBMISSION
1.08 <u>CBI</u>	CBI Certification — If you had certify that the following stathose confidentiality claims we "My company has taken measures and it will continue to take the been, reasonably ascertainable using legitimate means (other a judicial or quasi-judicial prinformation is not publicly aw would cause substantial harm to	tements to hich you to prote hese meas to by other than discordeding tailable e	ruthfully and accurately have asserted. ct the confidentiality o ures; the information is persons (other than govovery based on a showing) without my company's colsewhere; and disclosure	f the information, not, and has not ernment bodies) by of special need in onsent; the of the information
	NAME	-	SIGNATURE	DATE SIGNED
	TITLE	_ (TELEPHONE NO.	
	fark (X) this box if you attach			

INC
_1 <u>5</u> ;]
ΔιΝι
11_
51719
<u> </u>
71312
] <u>N</u> 1 <u>7</u> 2
INIÆ
_1 <u>517</u>
AINID
_1_1_
17191
12151
2

PART	B CORPORATE DATA
1.09	Facility Identification
<u>CBI</u>	Name []]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
	(_ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _
	[]]]] [0]]]][]]][]]]] State
	Dun & Bradstreet Number $$
	EPA ID Number
	Employer ID Number
	Primary Standard Industrial Classification (SIC) Code[질]고]
	Other SIC Code
	Other SIC Code
1.10	Company Headquarters Identification
CBI	Name [_ _ _ _ _ _ _ _ _ _ _ _ _
[_]	Address [_]_]_]_]_]_]_]_]_]]]]]]]]]]]]]]]]]]]
	(_ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ <u> </u>
	[<u>四</u> 乗] (<u> </u> 0 <u> </u> 1 <u> </u> 7 <u> </u> 7 <u> </u> 7 <u> </u> 1 1 1 1 1 1 1 1 1 1 1 1 1
	Dun & Bradstreet Number
	Employer ID Number [4]2]4]5]6]2]2[5]
tl	Mark (X) this box if you attach a continuation sheet.

PART	B CORPORATE DATA
1.09	Facility Identification
<u>CBI</u> [_]	Name []]]]]]]]]]]]]] [] []
1.10	Company Headquarters Identification
<u>CBI</u>	Name [][][][][][][][][][][][][][][][][][][]
	Dun & Bradstreet Number [②]②]-[②]③]-[②]④][②][②][②][②][②][②][②][②][②][②][②][②][③][②][②][②][②][②][③][②][②][②][③][②][③][②][③][②][③][②][③][②][②][③][②][③][③][③][③][③][③][③][③][③][③][③][③][③]
[_]	Mark (X) this box if you attach a continuation sheet.

1.11	Parent Company Identification
<u>CBI</u>	Name [7]]]]]]]]]]]]]]]]]]]
	[_ _]_ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _ _
	[_]_] [_]_]_]_]_]_]-[_]_]_]_]_] State
	Dun & Bradstreet Number[_]_]-[_]]-[_]]-[_]]-[_]]]
1.12	Technical Contact
<u>CBI</u>	Name []]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
	City
	[M]A] [O]Z[3]7]0][]]]] State Telephone Number
1.13	This reporting year is from
	Mark (X) this box if you attach a continuation sheet.

1.14	Facility Acquired If you purchased this facility during the reporting year, provide the following information about the seller:
CBI	Name of Seller [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_] [_]_]_]_]_][_]_]_]_]_ State
	Employer ID Number
	Date of Sale
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
1.15	Facility Sold If you sold this facility during the reporting year, provide the following information about the buyer:
CBI	Name of Buyer [_]_]_]_]_]_]_]_]_]_]_]_]_]_]
[_]	Mailing Address [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	[_]_] [_]_]_]_]_]]_]_]_]_] State
	Employer ID Number
	Date of Purchase
	Contact Person [_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
	Telephone Number
[_]	Mark (X) this box if you attach a continuation sheet.

Classification	Quantity (kg/
Manufactured	NA
Imported	
Processed (include quantity repackaged)	208211
Of that quantity manufactured or imported, report that quantity:	
In storage at the beginning of the reporting year	<u>NA</u>
For on-site use or processing	<u>NA</u>
For direct commercial distribution (including export)	<u>NA</u>
In storage at the end of the reporting year	<u>NA</u>
Of that quantity processed, report that quantity:	
In storage at the beginning of the reporting year	UIC
Processed as a reactant (chemical producer)	* * * * * * * * * * * * * * * * * * *
Processed as a formulation component (mixture producer)	110
Processed as an article component (article producer)	
Repackaged (including export)	μ t Δ
In storage at the end of the reporting year	
In storage at the end of the reporting year	
	•

Classification	Quantity (kg/yr)
	AiA
Manufactured	4.0
Imported	
Processed (include quantity repackaged)	<u> </u>
Of that quantity manufactured or imported, report that quan	ntity:
In storage at the beginning of the reporting year	<u>NA</u>
For on-site use or processing	<u>NA</u>
For direct commercial distribution (including export)	<u>NA</u>
In storage at the end of the reporting year	<u>NA</u>
Of that quantity processed, report that quantity:	
In storage at the beginning of the reporting year	
Processed as a reactant (chemical producer)	
Processed as a formulation component (mixture producer)	A
Processed as an article component (article producer)	128306
Repackaged (including export)	
In storage at the end of the reporting year	****
- The state of the separating four treatments	
	•

EDGEWATER

1.16	For each classification listed below, state the quantity of the lister was manufactured, imported, or processed at your facility during the	ed substance that reporting year.
CBI	Classification	Quantity (kg/yr)
	Manufactured	<u>NA</u>
	Imported	<u>NA</u>
	Processed (include quantity repackaged)	3607/_
	Of that quantity manufactured or imported, report that quantity:	
	In storage at the beginning of the reporting year	<u>NA</u>
	For on-site use or processing	<u>NA</u>
	For direct commercial distribution (including export)	<u>NA</u>
	In storage at the end of the reporting year	<u>NA</u>
	Of that quantity processed, report that quantity:	4
	In storage at the beginning of the reporting year	<u>uk</u>
	Processed as a reactant (chemical producer)	
	Processed as a formulation component (mixture producer)	
	Processed as an article component (article producer)	<u>36071</u>
	Repackaged (including export)	<u>NA</u>
	In storage at the end of the reporting year	A - 1

[$\overline{}$] Mark (X) this box if you attach a continuation sheet.

.17 <u>BI</u>	Mixture If the listed substance on which you are required to report is a mixture or a component of a mixture, provide the following information for each component chemical. (If the mixture composition is variable, report an average percentage of each component chemical for all formulations.)				
_]	Component Name	Supplier Name		Composi (speci	verage % tion by Weigh fy precision, , 45% ± 0.5%)
7		PRUETT SCHAFFER	CHEM.		80%
	Z,4 - AND Z,6-ISOMERS Sucrose POLYETHER POLYOL	PRUETT SCHAFFER	CHEM		20%
			·	Total	100%

2.04	State the quantity of the listed substance that your facility man or processed during the 3 corporate fiscal years preceding the redescending order.	ufactured, i porting year	mported, in
<u>CBI</u>			
[_]	Year ending	[<u>0</u>] <u>7</u>]	[<u>天]</u>] Year
	Quantity manufactured	O	kg
	Quantity imported	O	kg
	Quantity processed	UK	kg
	Year ending	··· [<u>7</u>]7]	[8]6] Year
	Quantity manufactured	0	kg
	Quantity imported	0	kg
	Quantity processed	• • • •	kg
	Year ending	[<u></u>] 7] Mo.	[종]도 Year
	Quantity manufactured	0	kg
	Quantity imported		
		· ·	
	Quantity processed	UK	kg
2.05 CBI	Specify the manner in which you manufactured the listed substance appropriate process types.	Circle all	
[_]			
	Continuous process	• • • • • • • • • • • •	1
	Semicontinuous process		2
	Batch process	• • • • • • • • • • • •	3
[_]	Mark (X) this box if you attach a continuation sheet.		

Poci

2.06 CBI	Specify the manner in appropriate process ty		he listed substance.	Circle all
[_]	Continuous process .			•••••
	Semicontinuous process	5	•••••	• • • • • • • • • • • • • • • • • • • •
	Batch process		••••••	(3
2.07 CBI	State your facility's substance. (If you and question.)			
[_]	Manufacturing capacity	· · · · · · · · · · · · · · · · · · ·	••••••	NA kg/yı
	Processing capacity .	••••••	•••••	NA kg/yr
2.08 CBI	If you intend to incremanufactured, imported year, estimate the incovolume.	, or processed at any	time after your cur	rent corporate fiscal
[_]		Manufacturing Quantity (kg)	Importing Quantity (kg)	Processing Quantity (kg)
	Amount of increase	NA	NA	NA
	Amount of decrease	NA	<u>NA</u>	NA
[_]	Mark (X) this box if y	ou attach a continuat	ion sheet.	

2.09	listed substanc substance durin	argest volume manufacturing or processing proce e, specify the number of days you manufactured g the reporting year. Also specify the average s type was operated. (If only one or two opera	or processed number of h	the listed
<u>CBI</u>				
[_]	,		Days/Year	Average Hours/Day
	Process Type #1	(The process type involving the largest quantity of the listed substance.)	**	
		Manufactured	NA_	NA_
		Processed	239	
	Process Type #2	(The process type involving the 2nd largest quantity of the listed substance.)		
		Manufactured		_NA_
		Processed	_NA	_NA_
	Process Type #3	(The process type involving the 3rd largest quantity of the listed substance.)		
		Manufactured	NA_	NA_
		Processed	NA_	_NA
2.10 <u>CBI</u> [_]	substance that we chemical. Maximum daily in	um daily inventory and average monthly inventory was stored on-site during the reporting year in oventory	the form of	ted a bulk 70 kg
[_]	Mark (X) this bo	ox if you attach a continuation sheet.	***************************************	

2.06 CBI	Specify the manner in appropriate process t	which you processed types.	the listed substance.	Circle all
[_]	Continuous process .	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	•••••
	Semicontinuous process	s	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •
	Batch process	•	•••••	
2.07 CBI	State your facility's substance. (If you and question.)	name-plate capacity free a batch manufacture	or manufacturing or er or batch processor	processing the listed , do not answer this
[_]	Manufacturing capacity	,	•••••	NA kg/yr
	Processing capacity .	••••••	•••••	Kg/yr
2.08 CBI	If you intend to incremanufactured, imported year, estimate the incovolume.	l, or processed at any	time after your cur	ent corporate fiscal
[_]		Manufacturing Quantity (kg)	Importing Quantity (kg)	Processing Quantity (kg)
	Amount of increase	NA	NA	NA
	Amount of decrease	NA	NA	NA
[_]	Mark (X) this box if y	ou attach a continuat	ion sheet.	

2.09	listed substand substant	argest volume manufacturing or processing proce e, specify the number of days you manufactured g the reporting year. Also specify the average s type was operated. (If only one or two opera	or processed number of h	the listed ours per
<u>CBI</u>				
[_]			Days/Year	Average Hours/Day
	Process Type #1	(The process type involving the largest quantity of the listed substance.)		
		Manufactured	NA_	NA_
		Processed	239	16
	Process Type #2	(The process type involving the 2nd largest quantity of the listed substance.)		
		Manufactured		_NA_
		Processed	NA_	_NA_
	Process Type #3	(The process type involving the 3rd largest quantity of the listed substance.)		
		Manufactured	NA_	_NA_
		Processed	NA_	_NA_
2.10 CBI	State the maximum substance that the chemical.	um daily inventory and average monthly inventory was stored on-site during the reporting year in	y of the lis the form of	ted a bulk
	Maximum daily in	nventory		<u>Z kg</u>
	Average monthly	inventory	106	9 <u>7</u> kg
	Mark (X) this bo	ox if you attach a continuation sheet.		

		FC		
2.06 CBI	Specify the manner in appropriate process t		the listed substance.	Circle all
[_]	Continuous process .			•••••
	Semicontinuous proces	S	• • • • • • • • • • • • • • • • • • • •	••••••
	Batch process			•••••••••••••••••••••••••••••••••••••••
2.07 <u>CBI</u>	State your facility's substance. (If you a question.)	name-plate capacity re a batch manufacture	for manufacturing or per or batch processor,	rocessing the listed do not answer this
[_]	Manufacturing capacit	y		kg/y
	Processing capacity	• • • • • • • • • • • • • • • • • • • •		kg/y
2.08 CBI	If you intend to incremanufactured, imported year, estimate the involume.	d, or processed at any	y time after your curr	ent corporate fiscal
	manufactured, imported year, estimate the ind	d, or processed at any	y time after your curr	ent corporate fiscal
<u>CBI</u>	manufactured, imported year, estimate the ind	d, or processed at any crease or decrease bas Manufacturing	y time after your curresed upon the reporting Importing	ent corporate fiscal year's production Processing
<u>CBI</u>	manufactured, imported year, estimate the incommendate th	d, or processed at any crease or decrease base Manufacturing Quantity (kg)	Importing Quantity (kg)	ent corporate fiscal year's production Processing Quantity (kg)
<u>CBI</u>	manufactured, imported year, estimate the involume. Amount of increase	d, or processed at any crease or decrease base. Manufacturing Quantity (kg)	time after your curred upon the reporting Importing Quantity (kg)	ent corporate fiscal year's production Processing Quantity (kg)
<u>CBI</u>	manufactured, imported year, estimate the involume. Amount of increase	d, or processed at any crease or decrease base. Manufacturing Quantity (kg)	time after your curred upon the reporting Importing Quantity (kg)	ent corporate fiscal year's production Processing Quantity (kg) 36000
<u>CBI</u>	manufactured, imported year, estimate the involume. Amount of increase	d, or processed at any crease or decrease base. Manufacturing Quantity (kg)	Importing Ouantity (kg)	ent corporate fiscal year's production Processing Quantity (kg) 36000
<u>CBI</u>	manufactured, imported year, estimate the involume. Amount of increase	d, or processed at any crease or decrease base. Manufacturing Quantity (kg)	Importing Ouantity (kg)	ent corporate fiscal year's production Processing Quantity (kg) 36000
<u>CBI</u>	manufactured, imported year, estimate the involume. Amount of increase	d, or processed at any crease or decrease base. Manufacturing Quantity (kg)	Importing Ouantity (kg)	ent corporate fiscal year's production Processing Quantity (kg) 36000

[] Mark (X) this box if you attach a continuation sheet.

2.09	listed substanc substance durin	argest volume manufacturing or processing proce e, specify the number of days you manufactured g the reporting year. Also specify the average s type was operated. (If only one or two opera	or processed number of h	l the listed ours per
CBI				
[_]			_Days/Year	Average Hours/Day
	Process Type #1	(The process type involving the largest quantity of the listed substance.)		
		Manufactured	NA_	_NA_
		Processed	239	16
	Process Type #2	(The process type involving the 2nd largest quantity of the listed substance.)		
		Manufactured		_NA_
		Processed	NA_	<u> </u>
	Process Type #3	(The process type involving the 3rd largest quantity of the listed substance.)		
		Manufactured	NA_	NA_
		Processed	<u>NA</u>	_NA_
2.10 <u>CBI</u> []	substance that we chemical. Maximum daily in	am daily inventory and average monthly inventory was stored on-site during the reporting year in inventory	y of the lis the form of	ted a bulk kg
[_]	Mark (X) this bo	ox if you attach a continuation sheet.		

2.11	the listed su	act Types List any bubstance in concentratied, or processed. The	ons greater than 0.	.1 percent as it	is manufac-
CBI	means the sou	arce from which the bypoto the product (e.g.,	roducts, coproducts	s, or impurities	are made or
(<u> </u>	CAS No.	Chemical Name	Byproduct, Coproduct or Impurity ¹	Concentration (%) (specify ± % precision)	Source of By products, Co products, or Impurities

CAS No.	Chemical Name	Byproduct, Coproduct or Impurity ¹	Concentration (%) (specify ± % precision)	products, Co- products, or Impurities
NA	NA	<u>IVA</u>	NA	_NA_
<u> </u>	V	<u> </u>	V	<u> </u>

 $^{^{1}\}text{Use}$ the following codes to designate byproduct, coproduct, or impurity:

B = Byproduct
C = Coproduct
I = Impurity

2.12 <u>CBI</u> [_]	Existing Product Types imported, or processed the quantity of listed total volume of listed quantity of listed subslisted under column b., the instructions for fu	using the listed su substance you use f substance used duri stance used captivel and the types of e	bstance during the re or each product type ng the reporting year y on-site as a percent and-users for each pro-	eporting year. List as a percentage of the r. Also list the ntage of the value
	a.	b.	c.	d.
		% of Quantity		·
		Manufactured, Imported, or	% of Quantity Used Captively	
	Product Types ¹	Processed	On-Site	Type of End-Users ²
		100	140	
	X	100		
	<pre>Use the following code A = Solvent B = Synthetic reactant C = Catalyst/Initiator Sensitizer D = Inhibitor/Stabiliz Antioxidant E = Analytical reagent F = Chelator/Coagulant G = Cleanser/Detergent H = Lubricant/Friction agent I = Surfactant/Emulsif J = Flame retardant K = Coating/Binder/Adherent</pre>	/Accelerator/ er/Scavenger/ /Sequestrant /Degreaser modifier/Antiwear ier esive and additives	L = Moldable/Castable M = Plasticizer N = Dye/Pigment/Colo O = Photographic/Rep and additives P = Electrodepositio Q = Fuel and fuel ad R = Explosive chemic S = Fragrance/Flavor T = Pollution contro U = Functional fluid V = Metal alloy and W = Rheological modi X = Other (specify)	on/Plating chemicals dditives cals and additives chemicals ol chemicals ds and additives additives
	² Use the following code:	s to designate the	type of end-users:	
	<pre>I = Industrial CM = Commercial</pre>	CS = Consu H = Other	umer r (specify)	
[_]	Mark (X) this box if you	u attach a continua	tion sheet.	

2.13 <u>CBI</u> [_]	Expected Product Types Identify all product types which you expect to manufacture import, or process using the listed substance at any time after your current corporate fiscal year. For each use, specify the quantity you expect to manufacture import, or process for each use as a percentage of the total volume of listed substance used during the reporting year. Also list the quantity of listed substance used captively on-site as a percentage of the value listed under column b., and the types of end-users for each product type. (Refer to the instructions for further explanation and an example.)				
	a.	b.		c.	d.
	Product Types ¹	% of Quantity Manufactured, Imported, or Processed		% of Quantity Used Captively On-Site	Type of End-Users ²
	<u> </u>	100	<u> </u>	100	<u></u>
	1				
	A = Solvent B = Synthetic reactant C = Catalyst/Initiator Sensitizer D = Inhibitor/Stabiliz Antioxidant E = Analytical reagent F = Chelator/Coagulant G = Cleanser/Detergent H = Lubricant/Friction agent I = Surfactant/Emulsif J = Flame retardant K = Coating/Binder/Adh	c/Accelerator/ cer/Scavenger/ c/Sequestrant c/Degreaser demodifier/Antiwear cier desive and additives	L = N = O = O = P = R = S = U = V = X = X = O = X = X = O = X = X = O = O	Moldable/Castable Plasticizer Dye/Pigment/Color Photographic/Reprand additives Electrodeposition Fuel and fuel add Explosive chemical Fragrance/Flavor Pollution control Functional fluids Metal alloy and Rheological modification (specify)	als and additives chemicals l chemicals s and additives
	I = Industrial CM = Commercial	CS = Cons H = Othe	umer		
[_]	Mark (X) this box if yo	u attach a continua	tion	sheet.	

a.	b.	c.	d.			
		Average %				
	T' 1 D 1	Composition of	m 6			
Product Type ¹	Final Product's Physical Form ²	Listed Substance in Final Product	Type of End-Users			
X	<u>H</u>	5	CS			
Use the following of A = Solvent B = Synthetic react C = Catalyst/Initiat Sensitizer D = Inhibitor/Stabit Antioxidant E = Analytical reag F = Chelator/Coagult G = Cleanser/Deterg	tor/Accelerator/ lizer/Scavenger/ ent ant/Sequestrant	duct types: L = Moldable/Castabl M = Plasticizer N = Dye/Pigment/Colo O = Photographic/Rep and additives P = Electrodepositio Q = Fuel and fuel ad R = Explosive chemic S = Fragrance/Flavor	rant/Ink and add rographic chemic n/Plating chemic ditives als and additive			
<pre>H = Lubricant/Frict</pre>	ion modifier/Antiwear	T = Pollution contro	l chemicals			
agent I = Surfactant/Emul	aifian	U = Functional fluid				
		V = Metal alloy and a	additives fior			
K = Coating/Binder/	Adhesive and additive	W = Rheological modi s X = Other (specify)	BOATS			
	² Use the following codes to designate the final product's physical form:					
A = Gas		stalline solid				
B = Liquid	F3 = Gra					
C = Aqueous solutio						
D = Paste E = Slurry	G = Gel	er (specify)BOA				
F1 = Powder	n = 000	er (specify)				
³ Use the following codes to designate the type of end-users:						
I = Industrial	CS = Con:					
CM = Commercial	H = Othe	er (specify)				

2.15 CBI	Circ list	le all applicable modes of transportation used to delive ed substance to off-site customers.	r bulk shipments o	of the
[_]	Truc	kNA	• • • • • • • • • • • • • • • • • • • •	• • • •
	Rail	car	• • • • • • • • • • • • • • • • • • • •	• • • • ;
	Barg	e, Vessel	• • • • • • • • • • • • • • • • • • • •	• • • • .
	Pipe	line	• • • • • • • • • • • • • • • • • • • •	
	Plan	e		
	0the	r (specify)	• • • • • • • • • • • • • • • • • • • •	
2.16 CBI	or prof er	omer Use Estimate the quantity of the listed substance repared by your customers during the reporting year for a nd use listed (i-iv).	e used by your cus use under each cat	tomers egory
	Cate	gory of End Use		
	i.	Industrial Products		
		Chemical or mixture	* * * * * * * * * * * * * * * * * * * *	_ kg/yr
		Article	NA	_ kg/yr
	ii.	Commercial Products		
		Chemical or mixture	NA	_ kg/yr
		Article	NA .	_ kg/yr
	iii.	Consumer Products	-	
		Chemical or mixture	NA	_ kg/yr
		Article	NA	_ kg/yr
	iv.	<u>Other</u>		
		Distribution (excluding export)	NA	kg/yr
		Export	NA	_ kg/yr
		Quantity of substance consumed as reactant	208217	- kg/yr
		Unknown customer uses	NA	_ kg/yr
	Mark	(X) this box if you attach a continuation sheet.		

2.15 CBI	Circ.	le all applicable modes of transportation used to delive ed substance to off-site customers.	r bulk shipments o	of the					
[_]	Trucl	,NA	••••••	1					
	Raile	ear	••••••	2					
	Barge, Vessel 3								
	Pipe:	line	• • • • • • • • • • • • • • • • • • • •	4					
	Plane	· · · · · · · · · · · · · · · · · · ·	• • • • • • • • • • • • • • • • • • • •	5					
	0ther	(specify)	• • • • • • • • • • • • • • • • • • • •	6					
2.16 <u>CBI</u> []	or pr	omer Use Estimate the quantity of the listed substance repared by your customers during the reporting year for a duse listed (i-iv).	e used by your cus use under each cat	tomers egory					
~ ~	Categ	gory of End Use							
	i.	Industrial Products							
		Chemical or mixture	NA	_ kg/yr					
		Article	NA	_ kg/yr					
	ii.	Commercial Products							
		Chemical or mixture	NА	_ kg/yr					
		Article	NA	_ kg/yr					
	iii.	Consumer Products							
		Chemical or mixture	NA	_ kg/yr					
		Article	NA	kg/yr					
	iv.	<u>Other</u>							
		Distribution (excluding export)	NA	kg/yr					
		Export	NA	- kg/yr					
		Quantity of substance consumed as reactant	1283.06	kg/yr					
		Unknown customer uses		_ kg/yr					
[_]	Mark	(X) this box if you attach a continuation sheet.							

2.15 CBI	Circ list	le all applicable modes of transportation used to deliver ed substance to off-site customers.	bulk shipments	of the				
 []	Truc	ruck 1						
		Railcar						
		e, Vessel						
	Pipe	line	• • • • • • • • • • • • • • • •					
	Plan	e	• • • • • • • • • • • • • • •	5				
		c (specify)		_				
2.16 <u>CBI</u> []	or prof er	omer Use Estimate the quantity of the listed substance repared by your customers during the reporting year for used use listed (i-iv). Gory of End Use	used by your cu se under each ca	ustomers ategory				
	i.	Industrial Products						
		Chemical or mixture	NA	kg/yr				
		Article	NA	kg/yr				
	ii.	Commercial Products						
		Chemical or mixture	AN	kg/yr				
		Article	NA	kg/yr				
	iii.	—	NA	kg/yr				
	iii.	Article	NA NA	kg/yr kg/yr				
	iii.	Article Consumer Products	NA NA NA					
	iii.	Article Consumer Products Chemical or mixture	NA NA	kg/yr				
		Article Consumer Products Chemical or mixture	NA NA NA	kg/yr				
		Article Consumer Products Chemical or mixture	NA NA NA	kg/yr kg/yr				
		Article Consumer Products Chemical or mixture	NA NA NA	kg/yr kg/yr kg/yr				
		Article Consumer Products Chemical or mixture	NA NA NA	kg/yr kg/yr kg/yr kg/yr				

SECTION 3 PROCESSOR RAW MATERIAL IDENTIFICATION

PART	A GENERAL DATA					
3.01 <u>CBI</u>	Specify the quantity purchased and the average price paid for the listed substance for each major source of supply listed. Product trades are treated as purchases. The average price is the market value of the product that was traded for the listed substance.					
ι1	Source of Supply	Quantity (kg)	Average Price (\$/kg)			
	The listed substance was manufactured on-site.	NA	NA			
	The listed substance was transferred from a different company site.	NA	NA.			
	The listed substance was purchased directly from a manufacturer or importer.	208217	0.69			
	The listed substance was purchased from a distributor or repackager.	NA	NA			
	The listed substance was purchased from a mixture producer.	NA	NA			
3.02 CBI [_]	Circle all applicable modes of transportation used to your facility.					
_	Truck	•	~ _			
	Railcar Barge, Vessel		_			
	Pipeline					
	Plane					
	Other (specify)					
[_]	Mark (X) this box if you attach a continuation sheet.					

SECTION 3 PROCESSOR RAW MATERIAL IDENTIFICATION

PART	A GENERAL DATA		
3.01 <u>CBI</u>	Specify the quantity purchased and the average price for each major source of supply listed. Product trade The average price is the market value of the product substance.	es are treated as	purchases.
t1	Source of Supply	Quantity (kg)	Average Price (\$/kg)
	The listed substance was manufactured on-site.	NA	NA
	The listed substance was transferred from a different company site.	NA	NA
	The listed substance was purchased directly from a manufacturer or importer.	128306	0.69
	The listed substance was purchased from a distributor or repackager.	NA	NA
	The listed substance was purchased from a mixture producer.	NA	NA
3.02 <u>BI</u>	Circle all applicable modes of transportation used to your facility. Truck		
	Railcar		2
	Barge, Vessel	••••••	3
	Pipeline	• • • • • • • • • • • • • • • • • • • •	4
	Plane	•••••	5
	Other (specify)	• • • • • • • • • • • • • • • • • • • •	6
	Mark (X) this box if you attach a continuation sheet.		
	account a continuation sneet.		

SECTION 3 PROCESSOR RAW MATERIAL IDENTIFICATION

PART	A GENERAL DATA					
3.01 <u>CBI</u>	Specify the quantity purchased and the average price paid for the listed substance for each major source of supply listed. Product trades are treated as purchases. The average price is the market value of the product that was traded for the listed substance.					
L1	Source of Supply	Quantity (kg)	Average Price (\$/kg)			
	The listed substance was manufactured on-site.	NA	NA			
	The listed substance was transferred from a different company site.	NA	NA			
	The listed substance was purchased directly from a manufacturer or importer.	36072.	0.69			
	The listed substance was purchased from a distributor or repackager.	NA	<u>NA</u>			
	The listed substance was purchased from a mixture producer.	NA	NA			
3.02 CBI	Circle all applicable modes of transportation used to your facility. Truck	•••••••••••••••••••••••••••••••••••••••	1			
	Railcar Barge, Vessel					
	Pipeline		•			
	Plane					
	Other (specify)					
]	Mark (X) this box if you attach a continuation sheet.					

3.03 CBI	a.	Circle all applicable containers used to transport the listed substance to your facility.
[_]		Bags 1
		Boxes
		Free standing tank cylinders 3
		Tank rail cars 4
		Hopper cars 5
		Tank trucks 6
		Hopper trucks
		Drums
		Pipeline9
		Other (specify)10
	b.	If the listed substance is transported in pressurized tank cylinders, tank rail cars, or tank trucks, state the pressure of the tanks.
		Tank cylinders MA mmHg
		Tank rail cars MA mmHg
		Tank trucks MA mmHg
		((X) this box if you attach a continuation sheet

	cessed during the rep	Average % Composition	Amount
N	Manufacturer	(specify \pm % precision)	Processed (kg/yr) Z60771
_			
_			

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

	F	Notes		
PART	B RAW MATERIAL IN THE	FORM OF A MIXTURE		
3.04 <u>CBI</u>	of the mixture, the nam	me of its supplier(s) ition by weight of th	form of a mixture, list the or manufacturer(s), an esset listed substance in the orting year.	timate of the
l1	Trade Name	Supplier or Manufacturer	Average % Composition by Weight (specify ± % precision)	Amount Processed (kg/yr)
	NAFIL RESIN 6403	KRUETT SCHAFFER	(HEM 80%	1,60,387
			٠	

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

1		F C				
PART	B RAW MATERIAL IN THE	FORM OF A MIXTURE		333		
3.04 <u>CBI</u>	If you obtain the listed substance in the form of a mixture, list the trade name(s) of the mixture, the name of its supplier(s) or manufacturer(s), an estimate of the average percent composition by weight of the listed substance in the mixture, and the amount of mixture processed during the reporting year.					
	Trade Name NAFIL RESIN 6403	Supplier or Manufacturer RRUETT SCHAFFER	Average % Composition by Weight (specify ± % precision)	Amount Processed (kg/yr) 45090		
			·			
			*.·			

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

3.03 CBI	а.	Circle all applicable containers used to transport the listed substance to your facility.
[_]		Bags 1
		Boxes 2
		Free standing tank cylinders 3
		Tank rail cars 4
		Hopper cars 5
		Tank trucks 6
		Hopper trucks 7
		Drums
		Pipeline 9
		Other (specify)10
	b.	If the listed substance is transported in pressurized tank cylinders, tank rail cars, or tank trucks, state the pressure of the tanks.
		Tank cylinders
		Tank rail cars
		Tank trucks
[]	Mark	(X) this box if you attach a continuation sheet.

CBI r	eporting year in the for	e listed substance used as a remof a class I chemical, class by weight, of the listed subs	ss II chemical, or polymer, and
·_,		Quantity Used (kg/yr)	$\%$ Composition by Weight of Listed Substance in Raw Material (specify \pm % precision)
C:	lass I chemical	<u>NA</u>	
		NA	
		NA	
C	lass II chemical	260271	80%
		NA	
		<u> </u>	·
Po	olymer	NA	•
		<u> </u>	
		<u>NA</u>	

PART C RAW MATERIAL VOLUM	E	
CBI reporting year in th	f the listed substance used as a e form of a class I chemical, claion, by weight, of the listed sub	ss II chemical, or polymer, and
` '	Quantity Used (kg/yr)	<pre>% Composition by Weight of Listed Sub- stance in Raw Material (specify ± % precision)</pre>
Class I chemical	<u>NA</u> <u>NA</u>	
Class II chemical	<u>NA</u> 160,382	න <i>ී</i> ්
	NA NA	
Polymer	NA_	· .
	<u> </u>	

CBI repor	ting year in the fo	ne listed substance used as a prome of a class I chemical, cla by weight, of the listed sub	ss II chemical, or polymer, and
 1		Quantity Used (kg/yr)	$\%$ Composition by Weight of Listed Substance in Raw Material (specify \pm $\%$ precision
Class	I chemical	NA	(opening) <u>r</u> 10 precession
		<u> </u>	
Class	II chemical	45090	80%
		NA NA	·
Polyme	er	<u>NA</u>	
		NA	

SECTION	/.	DUVCTCAL	/CHEMICAL	PROPERTIES
SP.L. LITTIN	4	PHINILAL	. / L.Mr.PIIL.AI.	PRUPERITE

~		_		1	T					•	•		_	_
G	en	е	га	.1	1	ns	s C	п	ıс	τ	1	on	S	÷

If you are reporting on a mixture as defined in the glossary, reply to questions in Section 4 that are inappropriate to mixtures by stating "NA -- mixture."

For questions 4.06-4.15, if you possess any hazard warning statement, label, MSDS, or other notice that addresses the information requested, you may submit a copy or reasonable facsimile in lieu of answering those questions which it addresses.

PART	A PHYSICAL/CHEMICAL DA	TA SUMMARY		
4.01 <u>CBI</u>	Specify the percent pursubstance as it is many substance in the final import the substance, or	ufactured, imported, or product form for manuf	processed. Measure acturing activities,	the purity of the at the time you
l J		Manufacture	Import	Process
	Technical grade #1	NA % purity	NA % purity	_UK_% purit
	Technical grade #2	% purity	NA % purity	<u>UK</u> % purit
	Technical grade #3	% purity	NA % purity	UK % purit
	¹ Major = Greatest quan	tity of listed substanc	e manufactured, impor	ted or processed.
4.02	1Major = Greatest quant Submit your most recent substance, and for ever an MSDS that you develor version. Indicate where appropriate response.	tly updated Material Sa ry formulation containi oped and an MSDS develo	fety Data Sheet (MSDS ng the listed substanged by a different so) for the listed ce. If you posses urce, submit your
4.02	Submit your most recensubstance, and for ever an MSDS that you developersion. Indicate where	tly updated Material Sary formulation containioped and an MSDS develo	fety Data Sheet (MSDS ng the listed substanged by a different so has been submitted by) for the listed ce. If you posses urce, submit your circling the
4.02	Submit your most recensubstance, and for ever an MSDS that you developersion. Indicate when appropriate response.	tly updated Material Sary formulation containioped and an MSDS develother at least one MSDS	fety Data Sheet (MSDS ng the listed substanted by a different so has been submitted by) for the listed ce. If you posses urce, submit your circling the
4.02	Submit your most recent substance, and for ever an MSDS that you developerate version. Indicate where appropriate response. Yes	tly updated Material Sary formulation containioped and an MSDS develo	fety Data Sheet (MSDS ng the listed substanted by a different so has been submitted by) for the listed ce. If you posses urce, submit your circling the
4.02	Submit your most recent substance, and for ever an MSDS that you developerate version. Indicate when appropriate response. Yes	tly updated Material Sary formulation containing oped and an MSDS development one MSDS ther at least one MSDS	fety Data Sheet (MSDS ng the listed substanged by a different so has been submitted by) for the listed ce. If you posses urce, submit your circling the
4.02	Submit your most recent substance, and for ever an MSDS that you developerate version. Indicate when appropriate response. Yes	tly updated Material Sary formulation containioped and an MSDS develother at least one MSDS	fety Data Sheet (MSDS ng the listed substanged by a different so has been submitted by) for the listed ce. If you posses urce, submit your circling the

4.03	Submit a copy or reasonable facsimile of any hazard information (other than an MSDS) that is provided to your customers/users regarding the listed substance or any formulation containing the listed substance. Indicate whether this information has been submitted by circling the appropriate response.											
	Yes	•••••	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • • •							
	No	· · · · · · · · · · · · · · · · · · ·	•••••	•••••		(
4.04 <u>CBI</u> []	For each activity that uses corresponding to each physi listed. Physical states fo the time you import or begi manufacturing, storage, disfinal state of the product.	cal state of the r importing and n to process the posal and transp	listed sub processing listed sub ort activit	stance durinactivities a stance. Phy	ng the activit are determined sical states ermined using	y lat for						
	Activity	Solid	Slurry	Liquid	Liquified Gas	Gas						
	Manufacture	1	2	. 3	4	5						
	Import	1	2	3	4	5						
	Process	1	2	(3)	4	5						

1.

[_]	Mark	(X)	this	box	if	you	attach	a	${\tt continuation}$	sheet.
-----	------	-----	------	-----	----	-----	--------	---	----------------------	--------

Store

Dispose

Transport

4.05	Particle Size If the listed substance exists in particulate form during any of the
	following activities, indicate for each applicable physical state the size and the
	percentage distribution of the listed substance by activity. Do not include
	particles ≥10 microns in diameter. Measure the physical state and particle sizes for
	importing and processing activities at the time you import or begin to process the
CBI	listed substance. Measure the physical state and particle sizes for manufacturing
	storage, disposal and transport activities using the final state of the product.
ſ 7	

Physical State		Manufacture	Import	Process		Dispose	Transport	
Dust	<1 micron	NA_	<u>NA</u>	MA	<u>NA</u>	<u>NH</u>	NA_	
	1 to <5 microns							
	5 to <10 microns							
Powder	<1 micron							
	1 to <5 microns							
	5 to <10 microns							
Fiber	<1 micron							
	1 to <5 microns							
	5 to <10 microns							
Aerosol	<1 micron							
	1 to <5 microns							
	5 to <10 microns		<u> </u>	—	<u> </u>		<u></u>	

In	dicate the rate constants for the following tra	ansformation processes.	
a.	Photolysis:		
	Absorption spectrum coefficient (peak)	UK (1/M cm) at	r
	Reaction quantum yield, 6	<u>UK</u> at	n
	Direct photolysis rate constant, k_p , at	1/hr	lati
b.	Oxidation constants at 25°C:		
	For 10_2 (singlet oxygen), k_{ox}	UK	1
	For RO_2 (peroxy radical), k_{ox}	UK	1
c.	Five-day biochemical oxygen demand, BOD_5	UK	m
d.	Biotransformation rate constant:	•.	
	For bacterial transformation in water, k_b	CLK	1
	Specify culture		
e.	Hydrolysis rate constants:		
	For base-promoted process, k _B	UK	1.
	For acid-promoted process, k _A	UK	1.
	For neutral process, $k_{_{\rm N}}$	UK	1.
f.	Chemical reduction rate (specify conditions)_	UK	
			<u>.</u>
g.	Other (such as spontaneous degradation)	UK	
8.	other (such as spontaneous degradation)	<u> </u>	

Mark ()	X)	this	box	i f	vou	attach	а	continuation	sheet.	

PART	B	PARTITION COEFFICIENT	rs			
5.02	a.	Specify the half-li	ife of the listed substan	nce in the follo	wing medi	a.
		<u>Media</u>		Half-life (spe	cify unit	<u>s)</u>
		Groundwater		ul		
		Atmosphere		UIL		
		Surface water	-	UiC		
		Soil		UK		
	b.	Identify the listed life greater than 2	substance's known trans 4 hours.	formation produc	cts that l	have a half-
		<u>cas no.</u> 1321 - 38-6	Name Z,6-Toluene Duso- cyonate	Half-life (specify units)	in	Media UK
			- Egara re		in	
					in in .	
5.03			er partition coefficient		UK	at 25°(
5.04			partition coefficient, K			
5.05	Spec coef	ify the organic carb	on-water partition		UL	at 25°0
5.06	Spec	ify the Henry's Law	Constant, H	<u>U</u>	4	atm-m³/mole

36

Bioconcentration Factor	<u>Species</u>	Test ¹
	UK	<u> </u>
¹ Use the following codes to d	esignate the type of test:	
<pre>F = Flowthrough S = Static</pre>		

6.04 <u>CBI</u>	For each market listed below, state the listed substance sold or transfer		
[_]	Market	Quantity Sold or Transferred (kg/yr)	Total Sales Value (\$/yr)
	Retail sales	NA	NA
	Distribution Wholesalers		
	Distribution Retailers		
	Intra-company transfer		
	Repackagers		***************************************
	Mixture producers		
	Article producers		
	Other chemical manufacturers or processors		
	Exporters		
	Other (specify)	\downarrow	V
6.05 <u>CBI</u> [_]	Substitutes — List all known commercifor the listed substance and state the feasible substitute is one which is edin your current operation, and which reperformance in its end uses. Substitute U	e cost of each substitut conomically and technolo	 A commercially gically feasible to use
[_]	Mark (X) this box if you attach a cont	inuation sheet.	

SECTION 7 MANUFACTURING AND PROCESSING INFORMATION

General Instructions:


For questions 7.04-7.06, provide a separate response for each process block flow diagram provided in questions 7.01, 7.02, and 7.03. Identify the process type from which the information is extracted.

PART A MANUFACTURING AND PROCESSING PROCESS TYPE DESCRIPTION

7.01 In accordance with the instructions, provide a process block flow diagram showing the major (greatest volume) process type involving the listed substance.

CBI BOAT BUILDING (RIGID URETHANEFORM) Process type NAFILRESIN trepolymer (IDI) 7.2 7B MIXER 7.3

7.03 In accordance with the instructions, provide a process block flow diagram showing all process emission streams and emission points that contain the listed substance and which, if combined, would total at least 90 percent of all facility emissions if not treated before emission into the environment. If all such emissions are released from one process type, provide a process block flow diagram using the instructions for question 7.01. If all such emissions are released from more than one process type, provide a process block flow diagram showing each process type as a separate block.



7.04 CBI	process block	typical equipment types flow diagram(s). If a sess type, photocopy this	process block flow	, diagram is prov	dided for more
[_]	Process type		BOAT BUI	DING	
	Unit Operation ID Number 7.1 7.2 7.3 7.4	Typical Equipment Type BUCKET BUCKET BUCKET W/ MIXER MOLD	Operating Temperature Range (°C) Ambient Ambient Ambient	Operating Pressure Range (mm Hg) Atmos Atmos Atmos	Vessel Composition FRP FRP FRP
			·		
[_]	Mark (X) this	box if you attach a cont	inuation sheet.		

Kack

7.05	process block fl	ocess stream identified in your pow diagram is provided for more plete it separately for each products.	than one process type	
<u>CBI</u>		<u> </u>	•	\
[_]	Process type	BOAT BUILDING (RIGIO URETHAN	E FOAM)
	Process Stream ID Code 7A 78 7C 7D 7E 7F	Process Stream Description NAFIL RESIN (FOAMT) PREPOLYMER PREMIX URETHANE FOAM MIX FOAMT VAPORS PREMIX VAPORS FOAM MIX VAPORS	Physical State ¹ OL OL GU GU GU	Stream Flow (kg/yr) 26027 135416 395687 UK UK UK
		BAM MIX VAPORS	<u> </u>	<u> UK</u>
	GC = Gas (conder GU = Gas (uncond SO = Solid SY = Sludge or : AL = Aqueous lic OL = Organic lic	quid	l pressure) und pressure)	
[_]	Mark (X) this box	x if you attach a continuation sh	eet.	

7.05	process block	process stream identified in your particles of the following stream is provided for more complete it separately for each process.	than one process type	iagram(s). If a e, photocopy this
<u>CBI</u>		<u> </u>		•
[_]	Process type .	BOAT BUILDING (RIGID URETHAN	E FOAM)
	Process Stream ID Code 7A 7B 7C 7D 7E 7F 7G	Process Stream Description NAFIL RESIN (FOAMT) PREPOLYMER PREMIX URETHANE FOAM MIX FOAMT VAPORS PREMIX VAPORS FOAM MIX VAPORS FOAM MIX VAPORS	Physical State ¹ OL OL GU GU GU	Stream Flow (kg/yr) 160381 83445 243827 UK UK UK UK
	GC = Gas (cond GU = Gas (unco SO = Solid SY = Sludge or AL = Aqueous 1 OL = Organic 1	liquid	pressure) nd pressure)	
[_]	Mark (X) this b	ox if you attach a continuation she	eet.	

7.03	process block f	low diagram is provided for more mplete it separately for each pro-	than one process type	e, photocopy thi
<u>CBI</u>				\
[_]	Process type	BOAT BUILDING (KIGLO URETHAN	E HOAM)
	Process	·		
	Stream ID	Process Stream		Stream
	Code	Description	Physical State ¹	Flow (kg/yr)
	7A	NAFIL RESIN (FORM T)	OL_	45090
	<u> 78</u>	PREPOLYMER PREMIX	0L	23460
		URETHANE FOAM MIX	OL	68550
		FOANT VAPORS	<u>GU</u>	_UK_
	TE	PREMIX VAPORS	<u>Gu</u>	UK
	7F	FORM MIX VAPORS	<u>Gu</u>	_uk
	7G	FORM MIX VAPORS	GU	_UK
	1	**************************************		
	¹ Use the followi	ing codes to designate the physica	al state for each pro	cess stream:
		ensible at ambient temperature and		
	GU = Gas (uncor SO = Solid	ndensible at ambient temperature a	ind pressure)	
	SY = Sludge or AL = Aqueous li			
	OL = Organic li	quid		
	IL = Immiscible	e liquid (specify phases, e.g., 90	% water, 10% toluene)
			-	

this quest	ion and complete it separa	tely for each	process type.	cess type, photocop (Refer to the
Process ty				
a. Process	b.	c. Concen-	d. Other	e. Estimated
Stream ID Code	Known Compounds	(% or ppm)	Expected Compounds	Concentrations (% or ppm)
_7A	/ 1	80% (A)	WA (W	NA
	SUCROSE POLYETHER POLYOL		d) NA	NA
<u>78</u>	PREPOXYMER (FORM REGA	81.77%	MA	<u>NA</u>
	WATER	6.3%		
	BLOWING AGENT CATALYST	10.18% 0.95%		
<u>7C</u>	7a + 7B			
continued	below	·		
	this questinstruction Process ty a. Process Stream ID Code 7A	this question and complete it separal instructions for further explanation. Process type a. b. Process Stream ID Code Known Compounds 1 TA TOWENE DISSOCYANATE Suchose by ETHER POLYOL TB REPOYMER FOAMRESS SUFFACTANT WATER BLOWING AGENT CATALYST	this question and complete it separately for each instructions for further explanation and an example process type a. b. c. Process Stream ID Code Known Compounds (% or ppm) 7A TOWENE DISSCYANNTE 80 % (% or ppm) Sucrose by ETHER 20 % (% or ppm) TB REPXYMER (FORM REIN) 81.77% (6.3%	A. b. c. d. Process Stream ID Code Known Compounds¹ (% or ppm) Compounds TA TOWENE DISSOCYANATE 80% (% or ppm) NA Sucrose by ETHER POLYOL TB PREPAYMER (TOAMREM) 81.77% NA SUFFACTANT 0.80% DEDWING AGENT 10.18% CATALYST 0.95% V

	_	
7.06	(cont	inued)

¹For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column b. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number	Components of Additive Package	Concentration (% or ppm)
1		
2		
3		
4 .		
5		-
² Use the following code	s to designate how the concentration	n was determined:
A = Analytical result E = Engineering judgem		
³ Use the following code	s to designate how the concentratio	n was measured:
V = Volume W = Weight		
ark (X) this box if you		

8.01 CBI	which descri	bes the treatment pr	cocess used for	residuals ide	tment block flow diagramntified in question 7.01
[_]	Process type	<u>E</u>	POAT BUIL	DING	
	No	residuals	remain	after	process.
				•	

<u>I</u>	type.	(Refer to th	e instruction	estion and colors for further	mplete it sepa r explanation	rately for ea and an exampl	e.)
_]		type					
	a. Stream ID Code	b. Type of Hazardous Waste	C. Physical State of Residual ²	d. Known Compounds ³	Concentra- tions (% or ppm) ^{4,5,6}	f. Other Expected Compounds	g. Estimate Concen- trations (% or ppm
		· · · · · · · · · · · · · · · · · · ·					
							_
 5	continue						

8.05 (continued) ¹Use the following codes to designate the type of hazardous waste: I = Ignitable C = Corrosive R = ReactiveE = EP toxicT = ToxicH = Acutely hazardous ²Use the following codes to designate the physical state of the residual: GC = Gas (condensible at ambient temperature and pressure) GU = Gas (uncondensible at ambient temperature and pressure) S0 = SolidSY = Sludge or slurry AL = Aqueous liquid OL = Organic liquid IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

8.05 continued below

0.00 (00	8.0	5 (con	ti	nued)
----------	-----	-----	-----	----	------	---

For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column d. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number	Components ofAdditive Package		Concentrations (% or ppm)
1	NA		NA
		_	
2		_	
		_	
3			
3		_	
4		_	
		••••	
5			- <u>-</u>
	V		<u> </u>
⁴ Use the following codes A = Analytical result E = Engineering judgeme	to designate how the concentra	tion was	determined:
continued below	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		
	attach a continuation sheet.		

8.05 (continued	l)
-----------------	----

 $^{5}\mbox{Use}$ the following codes to designate how the concentration was measured:

V = Volume

W = Weight

⁶Specify the analytical test methods used and their detection limits in the table below. Assign a code to each test method used and list those codes in column e.

Code	Method	Detection Limit (± ug/l)
1	NA	NA
2	4	
3		
_4		
_5		
6	V	

8.06	diagram process	(s). If a retype, photoe	esidual trea copy this qu	atment block Jestion and o	flow diag complete i	ram is pro t separate	reatment blo vided for mo ly for each an example.)	re than one process		
<u>CBI</u>	Process type									
	a.	b.	c.	d.	e	? .	f.	g.		
	Stream ID Code	Waste Description Code	Management Method Code ²	Residual Quantities (kg/yr)	of Resi	agement dual (%) Off-Site	Costs for Off-Site Management (per kg)	Changes in Management Methods		
	··			-						
										
							descriptions			
[_]	Mark (X)) this box if	f you attach	ı a continuat	ion sheet	•				

8.22 Describe the combustion chamber design parameters for each of the three larges (by capacity) incinerators that are used on-site to burn the residuals identif your process block or residual treatment block flow diagram(s).					argest entified in		
[_]		ustion amber ture (°C)	b e r Temp		In Co	Residence Time In Combustion Chamber (seconds)	
	Incinerator	Primary	Secondary	Primary	Secondary	Primary	Secondary
	1	NA	NA	NA	NA	NA	NA
	2		Ì				
	3	1				—	
	by circl	ing the appr	ropriate resp	oonse.	s been submit	••••••	of response
<u>CBI</u>	Complete the fare used on-sitreatment bloc	te to burn t	the residuals ram(s). Air Po	identified llution Device	in your proc	ess block of Types Emissior Avail	residual s of ns Data
	1		N4	Δ		NA	
	2			·		Popular Mary	
	3			/		V	
	Indicate by circl	if Office o	of Solid Wast copriate resp	e survey has onse.	s been submit	ted in lieu	of response
	Yes	• • • • • • • • • •	• • • • • • • • • • • • •	• • • • • • • • • • •	• • • • • • • • • • • • •	• • • • • • • • • • • •	1
					• • • • • • • • • • • • • • • • • • • •		
	¹ Use the follow S = Scrubber (E = Electrosta	ving codes t (include typ atic precipi	o designate e of scrubbe tator	the air poll			
[_]	0 = Other (spe				eet.	Was villa and Articles Articles	9

PART A EMPLOYMENT AND POTENTIAL EXPOSURE PROFILE

	Mark (X) the appropriate column to indicate whether your company maintains records on the following data elements for hourly and salaried workers. Specify for each data
CBI	element the year in which you began maintaining records and the number of years the records for that data element are maintained. (Refer to the instructions for further explanation and an example.)

Ī	Oata are Ma Hourly	intained for: Salaried	Year in Which Data Collection	Number of Years Records
Data Element	Workers	Workers	Began	Are Maintained
Date of hire	_X_	X	1959	
Age at hire	<u>X</u>	<u>X</u>	1959	
Work history of individual before employment at your facility			1959	5
Sex	_X_	X	1959	5
Race	NA	NA_		NA_
Job titles	_NA_	X	1959	5
Start date for each job title	MA	NA_	NA	_NA
End date for each job title	_NA_	NA_	NA	
Work area industrial hygiene monitoring data		_X	1983	3
Personal employee monitoring data	NA_	_NA_	NA.	_NA
Employee medical history	X	<u> </u>	1989	5
Employee smoking history	IXA	NA	NA	-NA
Accident history	_X_	X	<u>un</u>	
Retirement date	_X_	X	1959	
Termination date	X	<u>X</u>	1454	
Vital status of retirees	NA	<u> NA</u>	<u> </u>	$-\frac{NH}{2}$
Cause of death data	NA	NA_	<u> </u>	<u> </u>

[]	Mark	(X)	this	box	if	you	attach	a	continuation	sheet.

Vaci-

02	in which you engage.	instructions, complete	the following ta	inte for ea	ach activity
<u>BI</u>	in which you engage.				
_]	a.	b.	c.	d.	e.
	Activity	Process Category	Yearly Quantity (kg)	Total Workers	Total Worker-Hours
	Manufacture of the	Enclosed	NA	NA	NA
	listed substance	Controlled Release			
		0pen			
	On-site use as	Enclosed			
	reactant	Controlled Release			<u> </u>
		0pen	208217	4_	6000
	On-site use as nonreactant	Enclosed	<u>NA</u>	NA	NA_
		Controlled Release		New York	
		0pen			
	On-site preparation of products	Enclosed			
	•	Controlled Release			
		0pen	<u> </u>	-V	

NA

9.02

CBI

in which you engage.

a. b. d. c. e. Yearly Total Total Activity **Process Category** Quantity (kg) **Vorkers** Worker-Hours Manufacture of the **Enclosed** listed substance Controlled Release 0pen On-site use as **Enclosed** reactant Controlled Release 0pen NA On-site use as **Enclosed** nonreactant Controlled Release 0pen On-site preparation **Enclosed** of products Controlled Release 0pen

In accordance with the instructions, complete the following table for each activity

CBI

[_]

In accordance with the in which you engage.	instructions, complete t	the following ta	ble for e	ach activity
a.	ь.	c.	d.	e.
Activity	Process Category	Yearly Quantity (kg)	Total <u>Workers</u>	Total Worker-Hours
Manufacture of the	Enclosed	NA	NA	NA
listed substance	Controlled Release			
	0pen			
On-site use as	Enclosed			
reactant	Controlled Release			
	0pen	36072	4	_8000_
On-site use as nonreactant	Enclosed	<u>NA</u>	NA_	_NA_
nonreactant	Controlled Release	• • •		
	0pen			
On-site preparation of products	Enclosed			
or products	Controlled Release			
	0pen	<u> </u>	\bot	V

.03 <u>BI</u>	Provide a descriptive encompasses workers what listed substance.	job title for each labor category at your facility that no may potentially come in contact with or be exposed to the
<u>_</u>]		
]	Labor Category	Descriptive Job Title
	A	Foam Compounder
	В	Pouring Crew
	С	Pouring Crew Group Leader
	D	Molding Asst Foreman
	Е	Molding Foreman
	F	
	G	
	Н	
	I	
	J	

In accordance with the instructions, provide your process block flow diagram(s) and indicate associated work areas. BOAT BUILDING (RIGID URETHAN FOAM) CBI Process type ATMOS ATMOS NAFILTERIN Premix (TDI) 7.1 7.2 COMPOUNDING 74 7B ATMOS MIXER 7.3 MIXING POURING (2 ATMOS Rigid Urethone Foam

(_)	Mark (X)	this box i	f you a ttach a	continuation	sheet.
[_]	Mark (X)	this box i	f you a ttach a	continuation	sheet.

CURING (3)

9.05 CBI	may potentially come in contact with or be exposed to the listed substance. Add any additional areas not shown in the process block flow diagram in question 7.01 or 7.02. Photocopy this question and complete it separately for each process type.					
[_]	Process type	BOAT BUILDING (RIGID URETHANE FOAM)				
	Work Area ID	Description of Work Areas and Worker Activities				
	1	DRIM STORAGE & DISPENSING (WORKERS WEIGHT				
	2	MIXING (WORKERS MIX COMPONENTS AND POUR INTO MOCDE)				
	3	MATERIAL CURES INSIDE MOLOS				
	4					
	5					
	6					
	7					
	8					
	9					
	10					
	10					
-						
[_]	Mark (X) this box if y	ou attach a continuation sheet.				

and complete	it separate	ely for	each process	type	and work a	•	-	
_		DONT	DUILD[49	(1.19/2)	URETHAN	IC TOP	
Work area	• • • • • • • • • •	• • • • • • •	• • • • • • • • • • • • •	• • • • •	• • • •			
Labor Category	Number of Workers Exposed	(Mode of Exposure e.g., direct kin contact)	;	Physical State of Listed ubstance	Average Length of Exposure Per Day ²	Numbe Days Yea Expo	
		In	halation	<u>.</u>	GUL	E	<u>Z1</u>	
A	l	Dire	ect Contac	-	04	B	Zf	
DE	Z	Inl	nalation		GU	B	2/	
			3713 (80.7)	TOLIN STATE OF THE				
				_				
					****	<u> </u>		
-								
-		***************************************						
GC = Gas (condensible at ambient temperature and pressure) GU = Gas (uncondensible at ambient temperature and pressure; includes fumes, vapors, etc.) SO = Solid Use the following codes to designate as A = 15 minutes or less B = Greater than 15 minutes, but not exceeding 1 hour			ent Sinian Alloient Olietc.) gnate average Dit not	SY = Sludge or slurry AL = Aqueous liquid OL = Organic liquid IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene) Everage length of exposure per day: D = Greater than 2 hours, but not exceeding 4 hours E = Greater than 4 hours, but not				
C = Greater t exceeding		ur, but	not	exc	eeding 8 he ater than	ours		

BOAT BUILDING (RIGID (RETHANE FOR
·····	
8-hour TWA Exposure Level (ppm, mg/m ³ , other-specify)	15-Minute Peak Exposure (ppm, mg/m³, other-spec
<u> </u>	UNK
<u> </u>	
,	
	• •
	8-hour TWA Exposure Level (ppm, mg/m ³ , other-specify)

9.06 CBI	come in conta and complete	itegory at your control of the separatel	ble for each wour facility the exposed to to	at encom he liste cess typ	passes worker d substance. e and work ar	rs who may pot Photocopy threa.	entially is question			
[_]	Process type		BOAT BUIL	DING	(RIGID U	RETHANE !	DAM)			
	Work area	• • • • • • • • • • • • • • • • • • • •	••••••			2				
	Labor Category B.C D.E	Number of Workers Exposed	Mode of Expos (e.g., di skin cont: Inhala Inhala	rect act) ·	Physical State of Listed Substance GU	Average Length of Exposure Per Day	Number of Days per Year Exposed			
	GC = Gas (contemperated GU = Gas (unitemperated Guille Gas (unitempera	exposure: ondensible at iture and pre icondensible iture and pre	essure) at ambient essure;	SY = AL = OL =	al state of Sludge or sludge Aqueous liqui Organic liqui Immiscible li	urry id id	ostance at			
	SO = Solid	oors, etc.)	(specify phases, e.g., 90% water, 10% toluene)							
	Use the following codes to designate average length of exposure per day:									
	<pre>A = 15 minutes or less B = Greater than 15 minutes, but not exceeding 1 hour C = Greater than one hour, but not exceeding 2 hours</pre>				<pre>D = Greater than 2 hours, but not exceeding 4 hours E = Greater than 4 hours, but not exceeding 8 hours F = Greater than 8 hours</pre>					
	Mark (X) this	box if you a	ttach a contin	uation sl	neet.					

For each labor category represented in question 9.06, indicate the 8-hour Time Weighted Average (TWA) exposure levels and the 15-minute peak exposure levels. Photocopy this question and complete it separately for each process type and work area.							
Process type	BOOT BUILDING	Prom URETHANE FRANCE					
	•	7					
work area							
Labor Category	8-hour TWA Exposure Level (ppm, mg/m ³ , other-specify)	15-Minute Peak Exposure Level (ppm, mg/m³, other-specify)					
_B, C	UNK	UNK					
D, E	UNK	UNK					
	Labor Category B, C D, E	B,C UNC					

9.06 CBI	each labor ca come in conta and complete	itegory at yo ict with or b it separatel	ur facility the exposed to to y	at encor he liste	npasses worke ed substance. De and work a	in question 9. rs who may pot Photocopy therea.	entially nis question
[_]	Process type		BOAT 1	DUILD	ing (Kie	GIDÜRETHA 3	NE HOAM
	Work area	• • • • • • • • • • • • • • • • • • • •		• • • • • • •		<u>3</u>	
	Labor Category B,C D,E	Number of Workers Exposed	Mode of Expos (e.g., di skin cont	rect act) iou	Physical State of Listed Substance GU GU	Average Length of Exposure Per Day	Number of Days per Year Exposed Z/G
	the point of GC = Gas (contempers GU = Gas (unitempers include SO = Solid	t ambient essure) at ambient essure; pors, etc.)	he physical state of the listed substance at SY = Sludge or slurry AL = Aqueous liquid OL = Organic liquid IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene) verage length of exposure per day: D = Greater than 2 hours, but not				
	B = Greater exceeding C = Greater exceeding		exceeding 4 hours E = Greater than 4 hours, but not exceeding 8 hours F = Greater than 8 hours				

9.07 CBI	Weighted Average (TW. Photocopy this quest area.	ory represented in question 9.06, A) exposure levels and the 15-min ion and complete it separately fo	ute peak exposure levels. or each process type and work
	Process type	BOAT BULDING (RE	GID CRETHANE FORM)
	Work area		3
	Labor Category	8-hour TWA Exposure Level (ppm, mg/m³, other-specify)	15-Minute Peak Exposure Level (ppm, mg/m³, other-specify)
	B, C	UNK	UNK
	D,E	UNK	UNK
[_]	Mark (X) this box if	you attach a continuation sheet.	

PART B WORK PLACE MONITORING PROGRAM

9.08 If you monitor worker exposure to the listed substance, complete the following table.

CBI

Sample/Test	Work Area ID	Testing Frequency (per year)	Number of Samples (per test)	Who Samples ¹	Analyzed In-House (Y/N)	Number of Years Records Maintained
Personal breathing zone	NA	NA	NA	NA_	NA	NA
General work area (air)				-	-	
Wipe samples						
Adhesive patches						
Blood samples						
Urine samples						
Respiratory samples						
Allergy tests						
Other (specify)						
Other (specify)						
Other (specify)	—		—	—		

 $^{^{1}\}mbox{Use}$ the following codes to designate who takes the monitoring samples:

- A = Plant industrial hygienist
- B = Insurance carrier
- C = OSHA consultant
- D = Other (specify)

f 1	Mark (V)	thia how	if you	-++h	_	continuation	
` <i>'</i>	nara (n)	tii15 ook	11 you	actach	a	continuation	sneet.

	Sample Type	Sa	mpling and Analyti	ical Methodol	ogy				
	NA	NA							
			1						
	\/		V						
	7.5	3 14 11			•				
9.10	If you conduct persor specify the following				substance,				
CBI			• • • • •						
_ [_]	Equipment Type ¹	Detection Limit ²	Manufacturer	Averaging Time (hr)	Model Number				
·,		NA		ITME (III)	MAA				
	<u> </u>	- <u>- NA</u> -	<u> </u>	<u> </u>					
				-					
	1/	1	3/						
	<u> </u>		<u> </u>						
	Use the following co A = Passive dosimete B = Detector tube C = Charcoal filtrat D = Other (specify) Use the following co E = Stationary monit F = Stationary monit G = Stationary monit H = Mobile monitorin I = Other (specify)	r ion tube with pump des to designate am ors located within ors located at plan g equipment (specif	work area facility t boundary	ing equipment	types:				
			tection limit uni						
	Use the following codes to designate detection limit units: A = ppm B = Fibers/cubic centimeter (f/cc) C = Micrograms/cubic meter (\(\mu/m\)^3)								

_] _]	Test Description	Frequency (weekly, monthly, yearly, etc.
. -	NA	NA
	1	
-		

Describe the engineering conto the listed substance. Plearness type and work area.				
Process type	BOAT	Bursing (Ri	GLD URETA	ANETOAM
Work area	• • • • • • • • • • • • • • • • • • • •			•
Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgraded
Ventilation:				
Local exhaust	<u> </u>	1960	/V	NA
General dilution	<u> </u>	1960		NA
Other (specify)		•		
N/A	\mathcal{N}	NA	_NA_	NA
Vessel emission controls	$\underline{\hspace{1cm}}$			
Mechanical loading or packaging equipment				
Other (specify)				
NA	\mathcal{N}	4	¥	\bigvee

2	Describe the engineering cont to the listed substance. Pho process type and work area.	trols that yo otocopy this	u use to reduce o question and comp	r eliminate won lete it separa	rker exposi tely for ea
		BOAT	Building (k	RIGID URETH	LANE FOR
	Work area Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgrade
	Ventilation:				
	Local exhaust	_ N	NA	NA	_NA
	General dilution		1960	<u> </u>	NA
	Other (specify)		·		
		N	<u>NA</u>	<u>MA</u>	NA
	Vessel emission controls	N			
	Mechanical loading or packaging equipment	N			
	Other (specify)	ιN	V	V	\bigvee

[[]_] Mark (X) this box if you attach a continuation sheet.

Describe the engineering co to the listed substance. I process type and work area.	hotocopy this	u use to reduce o question and comp	r eliminate wor lete it separat	ker exposu ely for ea
Process type	. BOAT BO	uiding (Rigi	D DRETHAN	E FOAM
Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgrade
Ventilation:				
Local exhaust	N	_NA	NA_	_NA_
General dilution	<u> </u>	1960	N	NA
Other (specify)				
	NA	_NA	NA	NA
Vessel emission controls				
Mechanical loading or packaging equipment				
Other (specify)	V	V	1	
				

[[]_] Mark (X) this box if you attach a continuation sheet.

Process typ	separately for each proces	ulding (Raid U	
Work area .		7.592	
			Reduction in Worl
***************************************	Equipment or Process Modif	ication	Exposure Per Year
	NA I		<u> </u>
		-	
		-	· · · · · · · · · · · · · · · · · · ·
		•	

9.13 CBI	Describe all equipment or process modifications you have a prior to the reporting year that have resulted in a reduct the listed substance. For each equipment or process modification to the percentage reduction in exposure that resulted. Photocomplete it separately for each process type and work area.	tion of worker exposure to fication described, state occupy this question and
	Process type BOAT BUILDING (RIGID URE	ETHANE FORM)
	Work area	1
	Equipment or Process Modification	Reduction in WorkerExposure Per Year (%)
	<u> </u>	NA
	V	V
		•
	Mark (X) this box if you attach a continuation sheet.	

<u>BI</u>	Process type Boat Bulding Rais	
1	Work area	3
	Equipment or Process Modification	Reduction in Worker Exposure Per Year (%)
	NA NA	NA
	V	
	•	

.14	in each work area in	order to reduce or eliminat	ipment that your workers wear or u te their exposure to the listed e it separately for each process t
<u> </u>		7 R	(0)
]	Process type	. DOAT DUILD	NG (RGID URETHANE FOAM
	Work area	••••••	
			Wear or
		Equipment Types	·Use (Y/N)
			<u> </u>
		Respirators	
		Safety goggles/glasses	<u> </u>
		Face shields	
		Coveralls	N
		Bib aprons	<u> </u>
		Chemical-resistant gloves	<u> </u>
		Other (specify)	
			N
			•

9.14 CBI	in each work are	a in order to reduce or elimina	dipment that your workers wear or use ate their exposure to the listed te it separately for each process type
	_	3. 3.	0 11 1
[_]	Process type	DOAT DUILDING	RIGID URETHANE FOAM)
	Work area	••••••	Z
		Equipment Types Respirators Safety goggles/glasses Face shields Coveralls Bib aprons Chemical-resistant gloves Other (specify)	Wear or Use (Y/N) Y IV N N
			·
	•	•	

9.14	in each work area	in order to reduce or eliminat	ipment that your workers wear or us te their exposure to the listed e it separately for each process ty
<u>CBI</u>	and work area.		
[_]	Process type	BOAT BUILDING	G (RIGID URETHANG FOAM
	Work area	• • • • • • • • • • • • • • • • • • • •	····3
			Wear or
		Equipment Types	Use (Y/N)
		Respirators	N
		Safety goggles/glasses	N
		Face shields	
		Coveralls	N
		Bib aprons	
		Chemical-resistant gloves	N
		Other (specify)	. ————
			\mathcal{N}

9.15	process respira tested,	ers use respirators when wor type, the work areas where tors used, the average usage and the type and frequency e it separately for each pro	the respirate, whether or of the fit	tors are us	sed, the type respirators w	of ere fit
CBI	Process	type BOAT BU	11. DINIG	RIGIAL	RETHANE	FOAM)
*	Work	Respirator	Average	Fit Tested	Type of	Frequency of Fit Tests
	Area	NEG AIR PRESSURE	Usage ¹	$\frac{(Y/N)}{Y}$	Fit Test ²	(per year)
	<u>2</u> 3		_A_	<u> </u>	<u> </u>	1
		NOTE: ALL RESPIR			N1054/	11<11
	E = Oth ² Use the QL = Qt	ekly	te the type	of fit tes	t:	
 [<u></u>]	Mark (X)	this box if you attach a co	ontinuation	sheet.		

Respirator ty					
	be –				
Type of Training ¹	Number of Workers Trained	Location of Training	Length of Training (hrs)	Person Performing Training	Fre
					
b.					
Respirator ty	pe	· • • • • • • • • • • • • • • • • • • •			
Type of Re-training	Number of Workers Re-trained	Location of Re-Training ²	Length of Re-Training (hrs)	Rerson Performing Re-Training	Fre
A = Outside B = In-house C = On-the-jo D = Other (s					
B = In-house C = On-the-jo D = Other (s	pecify)	to designate	the person who perf	orms the trainin	g or
B = In-house C = On-the-jo D = Other (s) 3 Use the following: A = Plant income B = Supervise C = Foreman	pecify)owing codes dustrial hygor	gienist	the person who perf		g or
B = In-house C = On-the-jo D = Other (s) 3 Use the follore-training: A = Plant inc B = Superviso C = Foreman D = Other (s)	pecify) owing codes dustrial hyg or pecify)	gienist			

9.19 <u>CBI</u>	Describe all of the work practices and administrative controls used to reduce or eliminate worker exposure to the listed substance (e.g., restrict entrance only to authorized workers, mark areas with warning signs, insure worker detection and monitoring practices, provide worker training programs, etc.). Photocopy this question and complete it separately for each process type and work area.					
[_]	Process type Boat Building (Rigid Urethane Foam)					
	Work area				, 2, 3	
	Respirator prote	ection				
				\\		
	Isolated area Laundering Servi	_ (Work f	frea 1 on	aly)		
	Laundering Servi	ce/Chan	ging room	ms		
,						
9.20	Indicate (X) how often you leaks or spills of the liss separately for each process	sted substance.	Photocopy thi area.	is question an	d complete it	
9.20	leaks or spills of the lisseparately for each process Process type Doa Work area	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times	rethane From 1 - 3	More Than 4	
9.20	leaks or spills of the lisseparately for each process Process type Doa: Work area	sted substance. ss type and work Biulding	Photocopy this area. Rigid U	rethane F	More Than 4	
9.20	Process type Doa: Work area Housekeeping Tasks Sweeping	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times Per Day	rethane From 1 - 3	More Than 4 Times Per Day	
9.20	leaks or spills of the lisseparately for each process Process type	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times	rethane From 1 - 3	More Than 4	
9.20	leaks or spills of the lisseparately for each process Process type Boa. Work area	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times Per Day	rethane From 1 - 3	More Than 4 Times Per Day	
9.20	leaks or spills of the lisseparately for each process Process type	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times Per Day	rethane From 1 - 3	More Than 4 Times Per Day	
9.20	leaks or spills of the lisseparately for each process Process type Boa. Work area	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times Per Day	rethane From 1 - 3	More Than 4 Times Per Day	
9.20	leaks or spills of the lisseparately for each process Process type Boa. Work area	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times Per Day	rethane From 1 - 3	More Than 4 Times Per Day	
9.20	leaks or spills of the lisseparately for each process Process type Boa. Work area	sted substance. ss type and work Building Less Than	Photocopy this area. Rigid U 1-2 Times Per Day	rethane From 1 - 3	More Than 4 Times Per Day	

9.21	Do you have a written medical action plan for responding to routine or emergency exposure to the listed substance?
	Routine exposure
	Yes 1
	No 2
	Emergency exposure
	Yes 1
	No 2
	If yes, where are copies of the plan maintained?
	Routine exposure:
	Emergency exposure:
9.22	Do you have a written leak and spill cleanup plan that addresses the listed substance? Circle the appropriate response.
	Yes
	No 2
	If yes, where are copies of the plan maintained?
	Has this plan been coordinated with state or local government response organizations? Circle the appropriate response.
	Yes
	No 2
9.23	Who is responsible for monitoring worker safety at your facility? Circle the appropriate response.
	Plant safety specialist 1
	Insurance carrier 2
	OSHA consultant 3
	Other (specify)4
[_]	Mark (X) this box if you attach a continuation sheet.

	Specify the exact location of your is located) in terms of latitude a (UTM) coordinates.	r facility (from cen and longitude or Un:	iversal Transvers	se Mercader
	Latitude		042.	10,00
	Longitude		070 . !	52, 48
	UTM coordinates Zone	, North	hing, Ea	asting
10.03	If you monitor meteorological condithe following information.	ditions in the vici	nity of your fact	ility, provide
	Average annual precipitation			inches/yea
	Predominant wind direction			
10.04	Indicate the depth to groundwater	below your facility	y.	
	Depth to groundwater			meters
	6 11 11 11 11 11 11 11 11 11 11 11 11 11			`
10.05 CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.)	indicate (Y/N/NA)	all routine relea	ases of the a definition o
	For each on-site activity listed, listed substance to the environment Y, N, and NA.)	indicate (Y/N/NA) ant. (Refer to the	all routine relea	a definition o
CBI	For each on-site activity listed, listed substance to the environment	indicate (Y/N/NA) ant. (Refer to the	all routine releatinstructions for	a definition o
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity	indicate (Y/N/NA) and the English	all routine releatinstructions for vironmental Relea	a definition of ase Land
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing	indicate (Y/N/NA) ant. (Refer to the Enter Air	all routine releatinstructions for vironmental Releater	a definition of ase Land
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing	indicate (Y/N/NA) ant. (Refer to the Enter Air	all routine releatinstructions for vironmental Releater	a definition of ase Land
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing	indicate (Y/N/NA) nt. (Refer to the Air NA VA	all routine releatinstructions for vironmental Releating Water NA NA NA	a definition of the same stand
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used	indicate (Y/N/NA) nt. (Refer to the Air NA V NA	all routine releatinstructions for vironmental Releating Water NA NA NA NA NA	a definition of the same stand
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage	indicate (Y/N/NA) nt. (Refer to the Air NA NA NA NA	all routine releatinstructions for vironmental Releating Water NA NA NA NA NA NA NA	a definition of the same stand with the same s
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	indicate (Y/N/NA) nt. (Refer to the En Air NA NA NA NA NA NA	all routine releatins for vironmental Releating Water NA NA NA NA NA NA NA NA NA N	a definition of the same stand with the same s
CBI	For each on-site activity listed, listed substance to the environment Y, N, and NA.) On-Site Activity Manufacturing Importing Processing Otherwise used Product or residual storage Disposal	indicate (Y/N/NA) nt. (Refer to the En Air NA NA NA NA NA NA	all routine releatins for vironmental Releating Water NA NA NA NA NA NA NA NA NA N	a definition of the same stand with the same s

Specify the exact location of your facility (from central point where process unit is located) in terms of latitude and longitude or Universal Transverse Mercader (UTM) coordinates.							
Latitude	• • • • • • • • • • • • • • • • • • • •	042.	09.42				
Longitude							
UTM coordinates Zor	ne, Nort	hing,	Easting				
If you monitor meteorological co	onditions in the vici	nity of your fa	cility, provide				
Average annual precipitation	•••••		inches/year				
Indicate the depth to groundwate	r below your facility	у.					
		•	meters				
For each on-site activity listed listed substance to the environm Y, N, and NA.)	, indicate (Y/N/NA) a ent. (Refer to the	all routine rele	eases of the a definition of				
On Cita Ashirian			ease				
	Air		Land				
· ·	<u>NA</u>	NA)					
Importing	<u>NA</u>	<u> </u>	<i>NA</i>				
Processing	У	N	N				
Otherwise used	NA	NA.	NA				
Product or residual storage	_NA	NA	NA				
Disposal	_NA_	NA	NA				
Transport	<u>NA</u>	NA	NA				
ark (X) this how if you attach a	continuation =====						
	Is located) in terms of latitude (UTM) coordinates. Latitude	is located) in terms of latitude and longitude or Un (UTM) coordinates. Latitude	is located) in terms of latitude and longitude or Universal Transve (UTM) coordinates. Latitude				

Vice as

SECTION 10 ENVIRONMENTAL RELEASE

General Instructions:

Complete Part E (questions 10.23-10.35) for each non-routine release involving the listed substance that occurred during the reporting year. Report on all releases that are equal to or greater than the listed substance's reportable quantity value, RQ, unless the release is federally permitted as defined in 42 U.S.C. 9601, or is specifically excluded under the definition of release as defined in 40 CFR 302.3(22). Reportable quantities are codified in 40 CFR Part 302. If the listed substance is not a hazardous substance under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and, thus, does not have an RQ, then report releases that exceed 2,270 kg. If such a substance however, is designated as a CERCLA hazardous substance, then report those releases that are equal to or greater than the RQ. The facility may have answered these questions or similar questions under the Agency's Accidental Release Information Program and may already have this information readily available. Assign a number to each release and use this number throughout this part to identify the release. Releases over more than a 24-hour period are not single releases, i.e., the release of a chemical substance equal to or greater than an RQ must be reported as a separate release for each 24-hour period the release exceeds the RQ.

For questions 10.25-10.35, answer the questions for each release identified in question 10.23. Photocopy these questions and complete them separately for each release.

10.01	Where is your facility located? Circle all appropriate responses.
<u>CBI</u>	
[_]	Industrial area
	Urban area
	Residential area
	Agricultural area
	Rural area
	Adjacent to a park or a recreational area
	Within 1 mile of a navigable waterway
	Within 1 mile of a school, university, hospital, or nursing home facility 8
	Within 1 mile of a non-navigable waterway 9
	Other (specify)10

10.02	Specify the exact location of your is located) in terms of latitude (UTM) coordinates.	is located) in terms of latitude and longitude or Universal Transverse Mercader						
	Latitude	••••••	<u> 28 </u>	5 , 15				
	Longitude 80 ° 52 , 00							
	UTM coordinates Zon	e, Nort	hing, E	asting				
10.03	If you monitor meteorological conthe following information.	nditions in the vici	nity of your fac	ility, provide				
÷	Average annual precipitation			inches/year				
	Predominant wind direction							
10.04	Indicate the depth to groundwater	r below your facility	7.					
	Depth to groundwater			meters				
10.05 CBI	For each on-site activity listed, listed substance to the environme Y, N, and NA.)	indicate (Y/N/NA) a ent. (Refer to the i	all routine releanns for	ases of the a definition of				
[_]	On Site Activity		rironmental Relea	ıse				
	On-Site Activity	Air	Water	Land				
	Manufacturing	NH NH	<u>NA</u>					
	Importing	NA NA	<u> </u>	<u>NA</u>				
	Processing	<u> </u>						
	Otherwise used	<u>NA</u>	<u> </u>	NA				
	Product or residual storage	NA	<u>NA</u>	NA				
	Disposal	<u>NA</u>	NA	NA				
	Transport	NA	<u>NA</u>	NA				
[<u></u>] M	fark (X) this box if you attach a	continuation sheet.						

<u>BI</u>	an example.)		
_1	Quantity discharged to the air	UK	kg/yr <u>+</u>
	Quantity discharged in wastewaters	NA	kg/yr ±
	Quantity managed as other waste in on-site treatment, storage, or disposal units	NA	kg/yr <u>+</u>
	Quantity managed as other waste in off-site treatment, storage, or disposal units	NA	kg/yr <u>+</u>
		* *	

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

10.08 CBI	for each process stre process block or resi	technologies used to minimize release cam containing the listed substance as dual treatment block flow diagram(s). Tately for each process type	identified in your Photocopy this question
[_]	Process type	BOAT BUILDING (RESIDE	IAL URETHANETO
	Stream ID Code	Control Technology NA	Percent Efficiency
	7F 7G		
			

.09 I	substance in	n terms of a Stream	tify each emission point source containing the listed ID Code as identified in your process block or diagram(s), and provide a description of each point
_]	source. Do	not include raw ma g., equipment leaks	terial and product storage vents, or fugitive emission. Photocopy this question and complete it separate.
			BUILDING (RIGID URETHANEFORM)
	Point Source ID Code	_	Description of Emission Point Source
	NA	_	NA
		_	
		_	
		_	
		_	
		_	

Mark (X) this

i f

Poir Sour II Coc	ce e	Physical State NA	Average Emissions (kg/day)	Frequency ² (days/yr) A	Duration ³ (min/day)	Average Emission Factor	Maximum Emission Rate (kg/min)	Maximum Emission Rate Frequency (events/yr)	Maximum Emission Rate Duration (min/even)
						_ <u> </u>	# * # T		_NA_
							-		

	_								
	_						·		
								-	
			•						
	_								
¹Use G =	the Gas	e following s; V = Vapor	codes to des	ignate physica ulate; A = Aero	l state at the osol; 0 = 0th	e point of re er (specify)	elease:		
				evel of emission					
					n				

production of listed substance)

	Point Source ID Code	Stack Height(m)	Stack Inner Diameter (at outlet) (m)	Exhaust Temperature (°C)	Emission Exit Velocity (m/sec)	Building Height(m)	Building Width(m)	Ver Typ
	NA	<u>NA</u>	NA	<u>NA</u>	NA	<u>IVA</u>	NA	M
							 -	
•	<u> </u>							
•								
					•			

_								
	¹ Height o	of attached	or adjacent	building				
	² Width of	attached o	or adjacent	building				
	³ Use the	following o	codes to des	ignate vent	type:			
	H = Hori V = Vert							

).12 <u>BI</u>	distribution for each Point Source	tted in particulate form, indicate the particle size ource ID Code identified in question 10.09. Implete it separately for each emission point source.					
<u>_</u>]	Point source ID code						
	Size Range (microns)	Mass Fraction (% \pm % precision)					
	< 1	NA					
	≥ 1 to < 10						
	≥ 10 to < 30						
	≥ 30 to < 50						
	≥ 50 to < 100						
	≥ 100 to < 500						
	≥ 500						
		Total = 100%					
		•					

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

PART	C	FUCITIVE	EMISSIONS
TIMI	v	TOGITIO	DISTORTING

10.13	types listed which are expeaced ing to the specified the component. Do this for residual treatment block from the exposed to the listed approcess, give an overall possible.	osed to the liveright percestor each procestor diagram(stance. It is not become the contract of the contract o	listed suent of these type is). Do note this itime per	bstance a le listed dentified lot includ s a batch year tha	and which substance in your e equipme or inter t the pro	are in se passing process b nt types mittently cess type	rvice through lock or that are operated is
CRT	exposed to the listed subst for each process type.	tance. Photo	copy thi	s questio	n and com	plete it	separately
CBI		7		10	e A	1 1 7	\
[_]	Process type	OST DW	LDING	(RIGI)	D URET	HANEL	DAM)
	Percentage of time per year type	r that the li	sted sub	stance is	exposed	to this p	rocess
						y Weight cess Stre	am
	Equipment Type	Less than 5%	5-10%	11-25%	26-75%	76-99%	Greater than 99%
	Pump seals ¹						
	Packed	NA	NA	NA	NA	NA	NA
	Mechanical		1	1		1	
	Double mechanical ²						
	Compressor seals ¹						
	Flanges						
	Valves						
	Gas ³						
	Liquid						
	Pressure relief devices ⁴ (Gas or vapor only)		_				
	Sample connections						
	Gas						
	Liquid						
	Open-ended lines ⁵ (e.g., purge, vent)						
	Gas						
	Liquid	<u> </u>	<u> </u>			$\underline{\hspace{1cm}}V$	$-V_{-}$
	List the number of pump an compressors	d compressor	seals, 1	ather tha	an the num	nber of pu	imps or
10.13	continued on next page						
[_] :	Mark (X) this box if you att	ach a contin	uation sh	neet.			

- ²If double mechanical seals are operated with the barrier (B) fluid at a pressure greater than the pump stuffing box pressure and/or equipped with a sensor (S) that will detect failure of the seal system, the barrier fluid system, or both, indicate with a "B" and/or an "S", respectively
- ³Conditions existing in the valve during normal operation
- ⁴Report all pressure relief devices in service, including those equipped with control devices
- ⁵Lines closed during normal operation that would be used during maintenance operations

10.14 Pressure Relief Devices with Controls -- Complete the following table for those pressure relief devices identified in 10.13 to indicate which pressure relief devices in service are controlled. If a pressure relief device is not controlled, enter "None" under column c.

a. Number of Pressure Relief Devices NA	b. Percent Chemical in Vessel ¹	Control Device	d. Estimated Control Efficiency ²
V			V

¹Refer to the table in question 10.13 and record the percent range given under the heading entitled "Number of Components in Service by Weight Percent of Listed Substance" (e.g., <5%, 5-10%, 11-25%, etc.)

[_]	Mark (X) this	box if	you	attach	а	continuation	sheet.	
-----	---------	--------	--------	-----	--------	---	--------------	--------	--

²The EPA assigns a control efficiency of 100 percent for equipment leaks controlled with rupture discs under normal operating conditions. The EPA assigns a control efficiency of 98 percent for emissions routed to a flare under normal operating conditions

place, complete the procedures. Photoco	following table re	garding tho nd complete	se leak dete it separat	ection and re ely for each	epair process
-V F			BOAT B	MOING	- 1
Process type	• • • • • • • • • • • • • • • • • • • •		(Right U	RETHANE	- TOAM)
Equipment Type	Leak Detection Concentration (ppm or mg/m³) Measured at Inches from Source	_	Frequency of Leak Detection	Repairs Initiated (days after	Repairs Completed
Pump seals					
-	NA	NA	NA	NA	NA
Mechanical	t		1		1
Double mechanical					
Compressor seals					
Flanges					
Valves					
Gas					
Liquid					
Pressure relief devices (gas or vapor only)					
Sample connections					
Gas					
Liquid					
Open-ended lines					
Gas					
Liquid _	V		-V	$\underline{\hspace{1cm}}$	V_{-}
POVA = Portable orga	nic vapor analyze		evice:		
	Place, complete the procedures. Photocotype. Process type Process type Equipment Type Pump seals Packed Mechanical Double mechanical Compressor seals Flanges Valves Gas Liquid Pressure relief devices (gas or vapor only) Sample connections Gas Liquid Open-ended lines Gas Liquid Open-ended lines Gas Liquid Open-ended lines Gas Liquid Open-ended lines Gas Liquid Open-ended lines Gas Liquid	place, complete the following table reprocedures. Photocopy this question a type. Process type	place, complete the following table regarding tho procedures. Photocopy this question and complete type. Process type	place, complete the following table regarding those leak det procedures. Photocopy this question and complete it separative. Process type	Process type

continuation

sheet

 $\widetilde{\mathbb{X}}$

this

10.16 CBI	liquid	raw mater	ntermediate a rial, interme atment block	ediate, and p	roduct s									
<u>un</u>	or res	idual (lea	TOMETIC DIOCK	rrow dragram	(5).				Operat-	_				
[_]					Vessel	Vessel	Vessel		ing	-				
` _		Floating	Composition	Throughput		Filling		Vessel		Vessel	Design	Vent	Control	Basis
	Vessel	Roof	of Stored	(liters		_							Efficiency	
	Type ¹	Seals ²	Materials ³	per year)	(gpm)	(min)	<u>(m)</u>	<u>(m)</u>	(1)	Controls *	<u>Rate</u>	(cm)	(%)	<u>Estimate</u> °
	NA	NA	_NA	NR	NA	NA	NA	NA	NA	NN	MA	NA	NA	NA
]	1		1	1	1	1	Ī						
	+						_	-					- ———	
					Ì									
											-		-	
													-	
		$\overline{}$						- 📙	_		- —		- —	
	4	$ \sqrt{} $	\bigvee	$\sqrt{}$	Ψ	Ψ	\forall	W	Ψ	Λ	\bigvee	\bigvee	Ψ	
				*							· — * —		-	

¹Use the following codes to designate vessel type:

F = Fixed roof

CIF = Contact internal floating roof

NCIF = Noncontact internal floating roof

EFR = External floating roof

P = Pressure vessel (indicate pressure rating)

H = Horizontal

U = Underground

²Use the following codes to designate floating roof seals:

MS1 = Mechanical shoe, primary

MS2 = Shoe-mounted secondary

MS2R = Rim-mounted, secondary

LM1 = Liquid-mounted resilient filled seal, primary

LM2 = Rim-mounted shield

LMW = Weather shield

VM1 = Vapor mounted resilient filled seal, primary

VM2 = Rim-mounted secondary

VMW = Weather shield

³Indicate weight percent of the listed substance. Include the total volatile organic content in parenthesis

⁴Other than floating roofs

⁵Gas/vapor flow rate the emission control device was designed to handle (specify flow rate units)

⁶Use the following codes to designate basis for estimate of control efficiency:

C = Calculations

S = Sampling

10.23 Indicate the date and time when the release occurred and when the release ceased or was stopped. If there were more than six releases, attach a continuation sheet and list all releases.

Time

(am/pm)

Release	Date Started	Time (am/pm)	Date Stopped
1	NA	NA	NA
2			
3			
4			
5			
6	\bigvee		$\overline{}$

10.24 Specify the weather conditions at the time of each release.

Release	Wind Speed (km/hr)	Wind Direction	Humidity (%)	Temperature (°C)	Precipitation (Y/N)
1					
2					
3					
4					
5					
6					

 $[\ \]$ Mark (X) this box if you attach a continuation sheet.

N44006300 BEST COPY AVAILABLE

MATERIAL SAFETY DATA SHEET

DOUCT NAME: 6403 NAFIL Resin

HMIS CODES: H F R P

PRODUCT CODE: 6403

===== SECTION I - MANUFACTURER IDENTIFICATION =========

MANUFACTURER'S NAME: PRUETT SCHAFFER CHEMICAL

ADDRESS: PRUETT SCHAFFER CHEMICAL Corp., P.O. Box 4350 Pgh. PA-15204 INFORMATION PHONE: 412-771-2000

EMERGENCY PHONE: 412-771-2000

DATE REVISED: 11-04-88 NAME OF PREPARER: Robert P. Barry

REASON REVISED: SARA Title III, Section 313 report requirements modification

====== SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION =======

OCCUPATIONAL EXPOSURE LIMITS VAPOR PRESSURE WEIGHT CAS NUMBER ACGINITIVE SECTION 313 REPORT OF HIS & TEMP PERCENT HAZARDOUS COMPONENTS

 Toluene Diisogramate (TDI) 2,4- and 2,5- isomers
 584-84-9
 0.005 pom
 Report Required
 0.0
 77F
 80

 Sucrose Polyether Polyol
 9049-71-2
 None known
 N/A
 20

This product may contain toxic chemicals subject to the reporting requirements of Section 313 of the Emergency Planning and Community Right-to-Know Act of 1986 and of 40 CFR 372. See "Hazardous Components" above for their identification.

========= SECTION III - PHYSICAL/CHENICAL CHARACTERISTICS

BOILING POINT: 484 degrees F.

SPECIFIC GRAVITY (H2O=1): 1.2

VAPOR DENSITY: HEAVIER THAN AIR

EVAPORATION RATE: SLOVER THAN ETHER

COATING V.O.C. : N/A

SOLUBILITY IN WATER: Reacts slowly with water to liberate CO2 gas.

APPEARANCE AND ODOR: Viscous, pale-yellow liquid with a pungent odor.

FLASH POINT: 260 F.

METHOD USED: FMMC

FLANMABLE LIMITS IN AIR BY VOLUME- LOWER: N/A UPPER: N/A

EXTINGUISHING MEDIA: FOAM, ALCOHOL FOAM, CO2, DRY CHEMICAL, WATER FOG, OTHER

SPECIAL FIREFIGHTING PROCEDURES

Wear self-contained breathing apparatus and full protective clothing. Highly toric gases and vapors may be generated by der modsition on combustion. Restrict area to all but essential personnel. Convict modify if cossible by dimina.

UNUSUAL FIRE AND EXPLOSION HAZARDS

DO MOT RESEAL CONTAINERS THAT HAVE BEEN CONTAMINATED WITH WATER; CO2 may be generated to bicsed container causing it be purst. Cool containers exposed to fine with water spray; material may self-oclyverize at temperatures higher than 350 F. **Year SCSA aft**er fire le exti**nguished, dangerous vapons may pe**nsist. Turrous gear ney need decoraamination before reuse.

MATERIAL SAFETY DATA SHEET

PAGE 2 OF 3

STABILITY: STABLE CONDITIONS TO AVOID

At temperatures above 350 deg F, material may self-polymerize. Keep containers tightly closed and away from moisture.

INCOMPATIBILITY (MATERIALS TO AVOID)

Contact with water, alcohols, amines, strong bases, metal compounds, surface active agents, and phosphorus compounds.

HAZARDOUS DECOMPOSITION OR BYPRODUCTS

Thermal decomposition may yield CO2, carbon monoxide, oxides of mitrogen, hydrogen cyanide, and toluene disocyanate.

HAZARDOUS POLYMERIZATION: MAY OCCUR

CO2 gas produced by self-polymerization at temperatures above 350 deg F may pressurize container resulting in rubture.

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Inhalation of toluene diisocyanate vapor above the Threshold Limit Value of .005 ppm may cause irritation of the respiratory tract, dryness of the throat, tightness in chest, or coughing. Symptoms may be immediate or delayed.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE

SKIN CONTACT: irritation, reddening, swelling, rash, scaling, or blistering; in severe cases dermatitis is possible. EYE CONTACT: tearing, reddening, swelling, stinging sensation. If left untreated,corneal damage or conjunctivitis may occur.

7 'N ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

\$... absorbtion may cause skin sensitization. Skin absorbtion of very small amounts of liquid or exposure to vapor of sensitized individuals may cause effects similiar to those identified under skin contact signs and symptoms.

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Can result in irritation and possible corrosive action in the mouth, stomach tissues, and digestive tract. Vomiting and diarrhea may result. No chronic health hazards are known resulting from ingestion.

HEALTH HAZARDS (ACUTE AND CHRONIC)

ACUTE: chest discomfort, coughing, shortness of breath, reduced lung function, asthma-like symptoms. Exposures well above the TLV may cause bronchitis, bronchial spasm, and pulmonary edema (fluid in lungs). These effects are reversible. CHRONIC: Repeated overexposure or a single large overexposure may produce sensitization (chemical asthma) to isocyanates or to other irritants. Decrease in lung function may be temporary or permanent. Flu-like symptoms have been reported.

CARCINOGENICITY: NTP? NO IARC MONOGRAPHS? NO OSHA REGULATED? NO The National Toxicology Program (NTP) lists TDI as a substance that may reasonably be anticipated to be carcinogenic. The IARC reports inadequate evidence for carcinogenicity in humans (IARC monograph 39). OSHA does not list TOI.

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE

Asthma, bromchitis, chromic respiratory disease, pre-existing specific isocyanate hypersensitivity, skim allergiss.

EMERGENCY AND FIRST AID PROCEDURES

EYES: flush with tepid water for 15 minutes. Obtain medical attention at once. SKIN: wash affected area with stac and water. Remove and wash contaminated clothing. INGESTION: DO NOT INDUCE VONITING. Consult physician. INWALATION: move to area free from risk of further exposure. Administer oxygen or artificial respiration as needed. Obtain medical attention Astumatic-type symptoms may develop and may be immediate or orleyed up to several nours. Treatment is essentially so matic. Once a person is diagnosed as sensitized to isocyanate, no further expressive can be permitted.

PAGE 3 OF 3

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Evacuate nonessential personnel. Dike material, prevent entry into sewers or waterways. Provide ventillation, wear respiratory protection. MAJDR SPILL: call Mobay Corp. at 412-923-1600. TRANSPORTATION SPILL: call CHEMIREC at 88-424-9300.

WASTE DISPOSAL METHOD .

Cover spill with absorbant material, pour dilute solution of ammonia/water over spill and let react for 10 minutes.

Shovel material into open top containers and add more decontamination solution. Remove containers to a safe clace, cover loosely, let stand for 48 hours. Wash down spill area. Dispose of waste in accordance with all governing regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Store between 70-90 deg F. Keep containers tightly closed. On not reseal a moisture-contaminated container. Naterial reacts slowly with water to generate CO2 gas, contaminated closed container may rupture. Average shelf life of this material is 6 months. TRAIN AND ECUCATE EMPLOYEES in the safe handling and use of this product, it is required by law.

OTHER PRECAUTIONS

DO NOT CUT, VELD, GRIND, SOLDER, OR BRAZE ON OR NEAR CONTAINER WHETHER FULL OR EMPTY. Do not reuse eapty containers. Do **not eat or smoke while using.** Medical supervision of employees who handle isocryanates is recommended. This should include **pre-employment** and periodic respiratory function tests (FEV,FVC minimum). Once a person has been diagnosed as sensitized to TDI, permit no further exposure. Exhaust air may need to be cleaned by scrubbers or filters to reduce environmental contamination. TDI exposure levels should be monitored by accepted techniques to ensure personnel safety.

FIRATORY PROTECTION

If airborne concentrations exceed the TLV or are not known, use a positive pressure air-supplied respirator, such as a Mine Safety Appliance #475217. TOI has poor warning properties since the odor at which it can be smelled is substantially higher than the TLV. At normal room temperatures, TOI levels quickly exceed the TLV when exposed to air.

VENTILATION

Ventilation sufficient to keep airborne concentrations of vapor and mist below the TLV's must be used. Refer to '
"Industrial Ventilation" published by the American Conference of Governmental Industrial Hygiensts for quidance.

PROTECTIVE GLOVES

Chemical resistant gloves(butyl rubber, nitrile rubber, polyvinyl alcohol)should be used. Do not rely on leather gloves.

EYE PROTECTION

Safety glasses, splash goggles, or full face shield should be used. Contact lenses should not be worn while handling.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT

Wear as much protective clothing as possible to minimize skin contact. At minimum use a full apron or coveralls if applying soray or foam. Wash contaminated clothing before reuse.

WORK/HYGIENIC PRACTICES

Emergency safety shower and eyebath should be available. Keep work area free of contaminated rags or empty containers.

CLAIMER

The information and recommendations contained herein were believed to be accurate at the time of preparation or obtained from sources believed to be generally reliable. Pruett Schaffer Chemical Corporation makes no warranty concerning train accuracy and will not be held trable for claims relating to any party's use of or reliance on this information.